

Basic Condition Guide

Report ID:	27,139,377	Version:	3
Created:	04 Nov 2025		


Make:	Holden	Model:	Colorado
Body Style:	Utility	Year:	2019
Rego No.:	LYB565	Rego Expiry:	13 Jan 2026
WoF Expiry:	05 Nov 2026	Odometer:	153,980 Kms
Good No.:	27139377	VIN:	MMU148MK0KH607770
Next Service:	164,000 Kms	Service History:	No

Noto:	This ro	nort ic	not a v	warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

General Comments

Under Carriera and Under Dannet Inches etien Comme	
Conditions During Body Inspection	Dry

Interior Comments Seats: Slight wear on drivers seat Carpets: Good Panels: Scuffs on right rear door card Dashboard: Good

Road Conditions During Test Drive Dry Engine Timing Mechanism Cambelt Evidence of Cam Belt Replacement Yes No 153,000 Kms Inspected by: Hoani Saunders Published by: Miroslav Granich Inspection Date: 22 Oct 2025

	OK	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	/		
Engine performance	/		
Noise	\(\frac{1}{V} \)		
Coolant condition	V		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			1
CV joints	V		
Wheel bearings	/		
Brakes		<u>. </u>	
Performance	V		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7.7 mm
Right front		8	3.1 mm
Left rear		7	7.3 mm
Right rear			7.0 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	V		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators			
Dashboard warning lights	V		
Wipers (front & rear)	/		
Window winder FL	V		
Window winder FR	V		
Window winder RL	/		
	<i>'</i>	ı	
Window winder RR	<i>V</i>		
Window winder RR Rear view mirrors			
Rear view mirrors	/		
Rear view mirrors Radio (basic test only)	<i>y</i>		
Rear view mirrors Radio (basic test only) CD (basic test only)	<i>y</i>		· ·
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	<i>V V</i>		· ·
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	<i>y y y</i> 2		<i>'</i>
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking	<i>y y y</i> 2		<i>'</i>
Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	<i>y y y</i> 2		<i>V</i>

I have read and understood this condition guide:

NAME SIGNATURE