

Basic Condition Guide

•	Report ID:	27,139,948	Version:	6
	Created:	30 Oct 2025		


Make: Toyota		Model:	Hilux	
Body Style:	Utility	Year:	2017	
Rego No.: KMF268		Rego Expiry:	12 Aug 2026	
WoF Expiry:	01 Aug 2026	Odometer:	386,141 Kms	
Good No.:	27139948	VIN:	MR0HA3CD800390525	
Next Service:	400,795kms	Service History:	No	

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

,				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Rear bumper plastic poor fitting.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

4x4 diesel auto d/cab ute.

ve Dry		
Timing Chain		
ent Yes No	Kms	
Daryll Timms		
Published by: Gemma Rowlands		
	Timing Chain ent Yes No	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tince{\tint{\text{\text{\text{\text{\text{\text{\text{\tin}\exitt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\exitit{\text{\tininte\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinit}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\text{\tinit}\\ \tinit}\\ \tittt{\text{\text{\text{\text{\text{\text{\ti}\til\titt{\text{\text{\text{\text{\text{\text{\tinit}\xi}\\ \tittt{\text{\text{\text{\text{\text{\texi}\tilit{\text{\text{\tex{\text{\texi}\til\titt{\text{\texi}\til\tiittt{\text{\text{\texi}\til\tintt{\text{\text{\texi}\tint{\text{\texi}\text{\t		
Radiator / Hoses (visual)	/		
Transmission			
Operation	V		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		9.0 mm
Right front			9.0 mm
Left rear			9.0 mm
Right rear			9.0 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance			
Shock absorbers			
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	·		
Wipers (front & rear)	· ·		
Window winder FL	·		
Window winder FR	/		
Window winder RL	· ·		
Window winder RR	·		
Rear view mirrors	·		
Radio (basic test only)	· ·		
CD (basic test only)	· ·		
Number of keys	2	<u> </u>	
Central locking			
Remote locking	· ·		
Sat. nav. (basic test only)	· /		
Reversing camera		-	
neversing carriera			

I have read and understood this condition guide:

NAME SIGNATURE