

Report ID:	27,140,692	Version:	2
Created:	05 Nov 2025		

Basic Condition Guide			Report ID: 27,140,692	
	umei	<u> </u>		Created: 05 Nov 2025
Make:	Toyota	Model:	Rav4	
Body Style:	SUV	Year:	2024	
Rego No.:	QSY625	Rego Expiry:	17 Jan 2026	Engine
WoF Expiry:	07 Aug 2027	Odometer:	28,202 Kms	Oil level
Good No.:	27140692	VIN:	JTMBW3FV70D241056	Smoke & fumes
Next Service:	40,000 kms		Yes	Engine performance
	,	Service History:	163	Noise
Note: This report is This report is a guide	•	le for age and mileage. I	Parts have not been dismantled or	Coolant condition
diagnostic testing ur	ndertaken. The vehicle ha b ection prior to purchase an	een driven up to 50km/	'h from cold. The Vendor recommends a	Cooling performance
Key				Radiator / Hoses (visual)
•	= Rust C = C	rack * = Deca	ls W = Significant scuffs	Transmission
D = Dent P	$\Gamma$ = Paint defect $P = P$	in dent SC = Stor	ne Chips	Operation
		S D		Noise
				Clutch
	(A)			CV joints
	Wheel bearings			
s				Brakes
				Performance
				Hand brake
	18			Tyres (lowest observed trea
				Left front
			(Q)	Right front
	$\angle$			Left rear
		D S		Right rear
Note: some defects	and blemishes may not be	displayed in the diagra	m	Spare
Body Inspecti	on Comments			Suspension
				Suspension performance
				Steering performance
				Shock absorbers
Conditions Dur	ring Body Inspection		Dry	Air Conditioning / Heater
Under Carriag	e and Under Bonnet	Inspection Comm	ents	Operation
				Electrical / Accessories
				Head lights
				Tail lights
				-

	01/	Requires	
Engine	OK	Attention	N/A
Oil level			
Smoke & fumes	<i>V</i>		
Engine performance			
Noise	\( \tau \)		
Coolant condition	•		
Cooling performance	•		
Radiator / Hoses (visual)	•		
Transmission	_	Ι	
Operation	•		
Noise	•		
Clutch			
CV joints	•		
Wheel bearings			
Brakes		I	
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		(	6.0 mm
Right front		6	6.0 mm
Left rear		6	6.0 mm
Right rear			6.0 mm
Spare	Yes		
Suspension			
Suspension performance	<b>✓</b>		
Steering performance	<b>/</b>		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	<b>✓</b>		
Tail lights	<b>✓</b>		
Indicators	<b>V</b>		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	<b>/</b>		
Window winder FR	/		
Window winder RL	/		
Window winder RR	<b>/</b>		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			~
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	1		

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain	1	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Marlon Espena			
Published by:	Syariah Saemo			
Inspection Date:	21 Oct 2025			

I have read and understood this condition guide:

**Interior Comments** 

**General Comments** 

Seats:

Carpets:

Panels:

Dashboard:

Good

Good

Good

Good