

Basic Condition Guide

Report ID:	27,141,798	Version:	3
Created:	11 Nov 2025		

OK

Requires Attention

N/A

	Mazda	Model:	CX-5
ody Style:	Wagon	Year:	2014
ego No.:		Rego Expiry:	
oF Expiry:		Odometer:	30,213 Kms
ood No.:	27141798	VIN:	7AT0C144X25115640
ext Service:	40,180 Kms	Service History:	No
	only. Consideration is ma		Parts have not been dismantled or 'h from cold. The Vendor recommends a
	ction prior to purchase ar		
/			
		Crack *= Deca	. 3
Dent PT	= Paint defect $P = R$	Pin dent SC = Sto	ne Cnips
SC		sc	D
	(O)=		SC
sc d			
\sim ρ	B		
14			S
— []			
	NO SE		
-			
	and blemishes may not b	e displayed in the diagra	m
ody Inspectio	on Comments		
			T_
	ing Body Inspection		Dry
nder Carriage	e and Under Bonne	t Inspection Comm	ients
nterior Comm	1		
nterior Comm	ents Good		
eats: arpets:	Good Good		
eats:	Good		
eats: arpets:	Good Good		
eats: arpets: anels:	Good Good Good		
eats: arpets: anels: ashboard:	Good Good Good		
eats: arpets: anels: ashboard:	Good Good Good		

Engine				
Oil level	/			
Smoke & fumes	/			
Engine performance	\(\times \)			
Noise	/			
Coolant condition	'			
Cooling performance	1			
Radiator / Hoses (visual)	~			
Transmission				
Operation	/			
Noise	1			
Clutch			V	
CV joints	1			
Wheel bearings	1			
Brakes				
Performance	1			
Hand brake	1			
Tyres (lowest observed tread of	depth of	tyres)		
Left front			5.0 mm	
Right front			1.5 mm	
Left rear			1.5 mm	
Right rear			5.0 mm	
Spare N/A				
Suspension				
Suspension performance	V			
Steering performance	1			
Shock absorbers	1			
Air Conditioning / Heater				
Operation	V			
Electrical / Accessories				
Head lights	V	1		
Tail lights	1			
Indicators	1			
Dashboard warning lights	1			
Wipers (front & rear)	1			
Window winder FL	1			
Window winder FR	1			
Window winder RL	1			
Window winder RR	1			
Rear view mirrors	1	<u> </u>		
Radio (basic test only)	1			
CD (basic test only)	1			
Number of keys	2	1		
Central locking	~			
Remote locking	1			
Sat. nav. (basic test only)	<i>\'\'</i>			
	<i>y</i>			
Reversing camera		<u> </u>		

I have read and understood this condition guide:

Lewis Dolamore

Shanna Bullion 04 Nov 2025

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Engine Timing Mechanism

Inspected by:

Published by:

Inspection Date:

Dry

Timing Chain

Yes

No

NAME SIGNATURE

Kms