

Report ID:	27,143,027	Version:	2
Created:	11 Nov 2025		

OK

Requires Attention

N/A

		Pagi	c Condition Guide	Report ID:	27,143	
	nue	<u> </u>		Created:	11 No	
Make:	Nissan	Model:	Elgrand			
Body Style:	Wagon	Year:	2010			
Rego No.:	HTQ220	Rego Expiry:	07 May 2026	Engine		
WoF Expiry:	29 Aug 2026	Odometer:	204,849 Kms	Oil level		
		VIN:	7AT0DH6MX14008567		Smoke & fumes	
Next Service:	214,000 kms	Service History:	No	Engine perfo		
lote: This report is	,	service mistory.	1,1,2	Noise		
his report is a guid	Coolant condition					
	ndertaken. The vehicle ha b ection prior to purchase an		h from cold. The Vendor recommends a or an additional charge.	Cooling pe	rforman	
(ey				Radiator / H	loses (vi	
S = Scratch R	Transmission					
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation		
	W	S D D	WSP	Noise	Noise	
-	Clutch					
			SPT	CV joints		
	Wheel bearings					
$b$				Brakes		
	Performance					
	Hand brake					
S SC	18			Tyres (lowest obser		
	Left front					
	Right front					
				Left rear		
R	W		W	Right rear		
Note: some defects	Spare					
Body Inspecti	on Comments			Suspension		
Tyre mobility ki	t available			Suspension perform		
				Steering performa		
				Shock abso	orbers	
Conditions Du	Air Conditioning /					
Under Carriag	Operation					
Fwd				Electrical /	Access	
				Head lights	5	
				Tail lights		
Interior Comr	Indicators					
Seats:	Dashboard warning					
Carpets:	Wipers (front & rea					
Panels:	Window winder FL					
Dashboard:	Tailgate trim scrat			Window wi	inder FR	
General Com				Window wi		
5.1.5. <b>5.1 5.5</b> 1111						

V	
V	
V	
V	
V	
V	
V	
V	
V	
	~
V	
~	
V	
V	
depth of tyres	;)
	6.0 mm
	6.0 mm
	4.0 mm
5.0 mm	
N/A	
~	
V	
V	
<b>/</b>	
V	
V	
V	
<b>/</b>	
V	
V	
~	
V	
V	
V	
V	
2	
~	
~	

I have read and understood this condition guide:

Admond Chan 10 Nov 2025

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Engine Timing Mechanism

Inspected by:

Published by:

Inspection Date:

Dry

Vasanthakumar Mayilswamy

Timing Chain

No

Yes

NAME

Kms