

# **Basic Condition Guide**

•	Report ID:	27,144,235	Version:	2
	Created:	30 Oct 2025		


Make: Mazda		Model:	Verisa
Body Style:	Hatchback	Year:	2006
Rego No.:	HPG744	Rego Expiry:	02 Feb 2026
WoF Expiry:	23 Sep 2026	Odometer:	182,775 Kms
Good No.:	27144235	VIN:	7AT0C103X14209064
Next Service:	172,200	Service History:	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

#### Kev

Rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

# **Body Inspection Comments**

**Bumper Partly Detached** 

Multiple Body Panels with Surface Rust, Engine Bay, Strut Towers - See Diagram

Conditions During Body Inspection	Wet		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments			
Seats:	Average		
Carpets:	Average		
Panels:	Average		
Dashboard:	Average		

## **General Comments**

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Can	n Belt Replacement	Yes No Kms
Inspected by:	Darren Beban	
Published by:	James Scott	
Inspection Date:	28 Oct 2025	

	ОК	Requires Attention	N/A
Engine			
Oil level	<b>/</b>		
Smoke & fumes	<b>/</b>		
Engine performance	~		
Noise	\( \frac{1}{V} \)		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	<b>✓</b>		
Transmission			
Operation	/		
Noise	<b>/</b>		
Clutch			<b>'</b>
CV joints	<b>/</b>		
Wheel bearings	<b>✓</b>		
Brakes			
Performance	<b>/</b>		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			1.0 mm
Right front			5.0 mm
Left rear			1.0 mm
Right rear			1.5 mm
Spare	Yes		
Suspension		ı	
Suspension performance	/		
Steering performance	/		
Shock absorbers			
Air Conditioning / Heater		ı	
Operation			
Electrical / Accessories		I	
Head lights			
Tail lights	<b>/</b>		
Indicators	<b>V</b>		
Dashboard warning lights			
Wipers (front & rear)	<b>/</b>		
Window winder FL	<b>V</b>		
Window winder FR	<b>V</b>		
Window winder RL			
Window winder RR	<i>\</i>		
Rear view mirrors	<i>V</i>		
Radio (basic test only)	<i>'</i>		
CD (basic test only)	1	<u> </u>	L
Number of keys	·	<u> </u>	<u> </u>
Central locking	-1		
Remote locking Sat. nav. (basic test only)			
Reversing camera	<b>/</b>		_
neversing carriera		L	

I have read and understood this condition guide:

NAME

SIGNATURE