

Basic Condition Guide


Report ID:	27,144,584	Version:	2
Created:	07 Nov 2025		

Make:	Nissan	Model:	Note		
Body Style:	Hatchback	Year:	2017		
Rego No.:		Rego Expiry:			
WoF Expiry:	06 Nov 2026	Odometer:	85,775 Kms		
Good No.:	27144584	VIN:	7AT0DH79X25121996		
Next Service:	94,700kms	Service History:	No		
Note: This report is not a warranty					
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a contract of the vehicle has been driven up to 50km/h from cold. The Vendor recommends are contract of the vehicle has been driven up to 50km/h from cold. The vendor recommends are contract of the vehicle has been driven up to 50km/h from cold. The vendor recommends are contract of the vehicle has been driven up to 50km/h from cold. The vehicle has been driven up to 50km/h from cold.					

full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = ScratchR = RustC = Crack* = DecalsW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Dry **Under Carriage and Under Bonnet Inspection Comments**

interior Commi	nterior Comments		
Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		

General Comments

NZ audio with apple car play + android auto. 360 degree camera.

		Dry
		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by: Marlor	n Espena	
Published by: Marce	l Elia	
Inspection Date: 06 No	v 2025	

	ОК	Requires Attention	
Engine		7100011011	,
Oil level	V		
Smoke & fumes	V		
Engine performance	V		
Noise	\(\frac{1}{2} \)		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	~		
Transmission			
Operation	>		
Noise	/		
Clutch			V
CV joints	✓		
Wheel bearings	/		
Brakes			
Performance	✓		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6.0 mm
Right front		6	6.0 mm
Left rear		7	7.0 mm
Right rear		7	7.0 mm
Spare	N/A		
Suspension	_	ı	
Suspension performance	/		
Steering performance			
Shock absorbers	•		
Air Conditioning / Heater		I	
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	•		
Indicators	V		
Dashboard warning lights			
Wipers (front & rear) Window winder FL	V		
Window winder FR Window winder RL	V		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	<i>V</i>		
CD (basic test only)			
Number of keys	2	<u> </u>	
Central locking	- -		
Remote locking	~		
Sat. nav. (basic test only)	_	 	
Reversing camera	1		<u> </u>
eversing culticia	_		

I have read and understood this condition guide:

NAME