

Basic Condition Guide

•	Report ID:	27,145,790	Version:	1
	Created:	22 Nov 2025		

	ntuei		ic Condition Guide	Created: 22 Nov 2025				
Make:	Mazda	Model:	Atenza	-		Requires	NI/A	
Body Style:	Sedan	Year:	2014	Engine	OK	Attention	N/A	
Rego No.:	NAE362	Rego Expiry:	20 Jun 2026	Oil level	· /			
WoF Expiry:	19 Nov 2026	Odometer:	164,002 Kms	Smoke & fumes	1			
Good No.:	27145790	VIN:	7AT0C139X20103862	Engine performance	1			
Next Service:	174,000 km	Service History:	No	Noise	1			
lote: This report is	,			Coolant condition	· /			
nis report is a guide iagnostic testing ur	e only. Consideration is mad ndertaken. The vehicle has l	de for age and mileage. P been driven up to 50km/	arts have not been dismantled or 'h from cold. The Vendor recommends a	Cooling performance	· /			
ıll mechanical insp	ection prior to purchase ar	nd this can be arranged —	for an additional charge.	Radiator / Hoses (visual)	1			
(ey		C	als W = Significant scuffs	Transmission				
	= Rust $C = 0$ T = Paint defect $P = 0$	Crack	Operation	· /				
			The Crips	Noise	1			
s sc	s	PSCSPSC		Clutch			1	
				CV joints	·			
	\sim		SPT	Wheel bearings	1			
SC C		<u> </u>		Brakes				
M	10 m		A A A A A A A A A A A A A A A A A A A	Performance	V			
1				Hand brake	1			
SD	HO !!			Tyres (lowest observed tread				
20 6				Left front	7 mm			
							7 mn	
				Right front				
DP		PSC SPSC	Left rear	7 mm				
			Right rear	7 mm				
	and blemishes may not b on Comments	e displayed in the diagr	am					
body ilispecti	on comments			Suspension	V			
				Suspension performance	'			
				Steering performance Shock absorbers	1			
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater				
	ge and Under Bonne	t Inspection Comp		· /				
Freshly service		t inspection conin	lients	Operation Electrical / Accessories				
New battery.	u.			V	1			
4 new tyres.	-		Head lights	V				
Front wheel driv				Tail lights	1			
Interior Comments				Indicators	<i>'</i>			
Seats:	Good			Dashboard warning lights				
Carpets: Good				Wipers (front & rear)	<i>V</i>			
Panels:	Good		Window winder FL	1	-			
Dashboard:	Good		Window winder FR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
General Comr New VTNZ war			Window winder RL	_	-			
ivew viiv∠ War	rant Or MHESS.			Window winder RR	<i>'</i>			
				Rear view mirrors	<i>V</i>			
D 10		D		Radio (basic test only)	V			
Road Conditions During Test Drive Dry				CD (basic test only)				
Engine Timing Mechanism Timing Chain				Number of keys	1			

I have read and understood this condition guide:

Inspection Date: 24 Oct 2025

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Imraan Bryant

Erin White

NAME

No

Yes

SIGNATURE

1

1

1

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms