

| Report ID: | 27,146,373  | Version: | 2 |
|------------|-------------|----------|---|
| Created:   | 04 Nov 2025 |          |   |

| Лake:  | Mitsubishi                     | Model:                  | Express  |  |  |  |
|--|--------------------------------|-------------------------|--|--|--|--|
| Body Style: Van Rego No.: NDY901 WoF Expiry: 16 Nov 2025 |                                | Year:                   | 2020   |  |  |  |
|  |                                | Rego Expiry:            | 15 Feb 2026<br>41,765 Kms  |  |  |  |
|  |                                | Odometer:               |  |  |  |  |
| Good No.:  | 27146373                       | VIN:                    | JMFKFL006LS000595  |  |  |  |
| Next Service:  | 51000                          | Service History:        | Yes  |  |  |  |
| agnostic testing u                                       | e only. Consideration is made  | oeen driven up to 50km/ | Parts have not been dismantled or<br>/h from cold. The Vendor recommends a<br>or an additional charge.   |  |  |  |
| ey   | '                              |                         |  |  |  |  |
|  | = Rust C = C                   |                         |  |  |  |  |
| = Dent P   | $\Gamma = Paint defect  P = P$ | in dent SC = Sto        | ne Chips   |  |  |  |
|  |                                | Р                       | P  |  |  |  |
|  |                                |                         | $\sim$   |  |  |  |
|  | > (O)=                         |                         | S  |  |  |  |
| s  |                                | <u> </u>                |  |  |  |  |
| M  | ID TO                          |                         | THE REPORT OF THE PERSON OF TH |  |  |  |
| 1  |                                |                         |  |  |  |  |
| sc   | 10 l                           |                         |  |  |  |  |
|  |                                |                         |  |  |  |  |
|  |                                | +                       | SD   |  |  |  |
|  |                                |                         |  |  |  |  |
| SC C   |                                | SD                      |  |  |  |  |
| ote: some defects  | and blemishes may not be       | displayed in the diagra | am   |  |  |  |
|  | on Comments                    |                         |  |  |  |  |
| Front bumper r   | <u> </u>                       |                         |  |  |  |  |
|  |                                |                         |  |  |  |  |
|  |                                |                         |  |  |  |  |
| Conditions Du  | ring Body Inspection           |                         | Dry  |  |  |  |
| Under Carriag  | e and Under Bonnet             | Inspection Comm         | nents  |  |  |  |
| -WD  |                                |                         |  |  |  |  |
|  |                                |                         |  |  |  |  |
|  |                                |                         |  |  |  |  |
| Interior Comn  | nents                          |                         |  |  |  |  |
|  | centre seat cushic             | on damage               |  |  |  |  |
| Seats:   | Carpets: Good                  |                         |  |  |  |  |
|  | Panels: Good                   |                         |  |  |  |  |
| Carpets:   | Good                           |                         |  |  |  |  |
| Carpets:   | Good<br>Good                   |                         |  |  |  |  |

|  | ОК  | Requires<br>Attention | N/A      |
|--|---|-----------------------|----------|
| Engine                                     |   |                       |          |
| Oil level                                  | /   |                       |          |
| Smoke & fumes                              | /   |                       |          |
| Engine performance                         | \( \text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tin}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texit{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\text{\ti}\text{\text{\ti}\tint{\text{\tin}\tint{\text{\text{\text{\text{\texi}\tinz{\text{\text{\text{\text{\texi}\tint{\text{\text{\text{\texi}\tint{\text{\texi}\tint{\text{\texi}\tilitt{\text{\tii}}\tint{\text{\text{\text{\tinit}\titt{\tinit}\tittt{\texi}\til\ti |                       |          |
| Noise                                      | /   |                       |          |
| Coolant condition                          | /   |                       |          |
| Cooling performance                        | /   |                       |          |
| Radiator / Hoses (visual)                  | /   |                       |          |
| Transmission                               |   | <u> </u>              |          |
| Operation                                  | /   |                       |          |
| Noise                                      | /   |                       |          |
| Clutch                                     |   |                       | ~        |
| CV joints                                  | /   |                       |          |
| Wheel bearings                             | /   |                       |          |
| Brakes                                     |   |                       |          |
| Performance                                | /   |                       |          |
| Hand brake                                 | /   |                       |          |
| Tyres (lowest observed tread dep           | pth of  | tyres)                |          |
| Left front                                 |   |                       | 1.5 mm   |
| Right front                                |   |                       | 1.5 mm   |
| Left rear                                  |   |                       | 6 mm     |
| Right rear                                 |   |                       | 7 mm     |
| Spare                                      | Yes   |                       |          |
| Suspension                                 |   |                       |          |
| Suspension performance                     | /   |                       |          |
| Steering performance                       | ~   |                       |          |
| Shock absorbers                            | ~   |                       |          |
| Air Conditioning / Heater                  |   |                       |          |
| Operation                                  | /   |                       |          |
| Electrical / Accessories                   |   |                       |          |
| Head lights                                | /   |                       |          |
| Tail lights                                | ~   |                       |          |
| Indicators                                 | /   |                       |          |
| Dashboard warning lights                   | /   |                       |          |
| Wipers (front & rear)                      | /   |                       |          |
| Window winder FL                           | /   |                       |          |
| Window winder FR                           | <b>/</b>  |                       |          |
| Window winder RL                           |   |                       | <b>V</b> |
| Window winder RR                           |   |                       | V        |
| Rear view mirrors                          | 1   |                       |          |
| Radio (basic test only)                    | /   |                       |          |
| CD (basic test only)                       |   |                       | <b>/</b> |
| Number of keys                             | 2   |                       |          |
| Central locking                            | /   |                       |          |
|  | 1   |                       |          |
| Remote locking                             |   |                       |          |
| Remote locking Sat. nav. (basic test only) |   |                       | <b>V</b> |

I have read and understood this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 04 Nov 2025

Engine Timing Mechanism

Inspected by:

Published by:

Dry Unknown

Arunachalam Subramanian

Arunachalam Subramanian

Yes

NAME

No

SIGNATURE

Kms