

•	Report ID:	27,148,841	Version:	5
	Created:	14 Nov 2025		

		Dooi	a Canditian Cuida	Report ID:	27,148,841
	nue	S Basi	c Condition Guide	Created:	14 Nov 202
Make:	Holden	Model:	Commodore		
Body Style:	Wagon	Year:	2012	Engine	
Rego No.:	GGR235	Rego Expiry:	13 Jan 2026	Oil level	
WoF Expiry:	24 Nov 2026	Odometer:	243,809 Kms	Smoke & fu	
Good No.:	27148841	VIN:	6G1EK8E37CL607089		
Next Service:	253,809 Kms	Service History:	Yes	Engine per	Tormance
Note: This report is	not a warranty	,		Noise	. dre
This report is a quide	only. Consideration is mad	e for age and mileage. Pa	arts have not been dismantled or n from cold. The Vendor recommends a	Coolant co	
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.		erformance
Key					Hoses (visual)
S = Scratch R	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion
D = Dent P	T = Paint defect P = P	in dent SC = Stor	ne Chips	Operation	
SC		SP SD	WSD	Noise	
$\overline{}$	$\overline{}$	\top		Clutch	
	\ \ <u>\</u>		SD	CV joints	
S SC W				Wheel bearings	
3 30 W				Brakes	
				Performan	ce
				Hand brak	e
SC				Tyres (low	est observed tr
				Left front	
			(Q)	Right front	:
				Left rear	
S SC		P PT P	W SD	Right rear	
Note: some defects	and blemishes may not be	e displayed in the diagra	ım	Spare	
Body Inspecti	on Comments			Suspensio	n
				Suspension	n performance
				Steering p	erformance
				Shock abso	orbers
Conditions Du	ring Body Inspection		Wet	Air Condit	tioning / Heat
Under Carriag	ge and Under Bonnet	Inspection Comm	nents	Operation	
				Electrical	/ Accessories
				Head light	

		Requires	
	ОК	Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	✓ ✓		
Engine performance	/		
Noise	V		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	✓		
Clutch			'
CV joints	/		
Wheel bearings	>		
Brakes			
Performance	✓		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			3.4 mm
Right front		3	3.8 mm
Left rear		(3.5 mm
Right rear		(3.3 mm
Spare	Yes		
Suspension			
Suspension performance	>		
Steering performance	>		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	>		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	>		
Radio (basic test only)	/		
CD (basic test only)	V		
Number of keys	2		
Central locking	/		
Remote locking	1		
Sat. nav. (basic test only)			~
Reversing camera	1		

Interior Comm	ents
Seats:	Stains. Wear on drivers seat and trim detached
Carpets:	Average
Panels:	Average
Dashboard:	Good
General Comm	nents

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Ryan Stanley	
Inspection Date:	30 Oct 2025	

have read and understood
this condition quide

NAME			