

Basic Condition Guide

Report ID:	27,149,442	Version:	2
Created:	06 Nov 2025		


Make:	Toyota	Model:	Wish
Body Style:	Wagon	Year:	2005
Rego No.:	LKU267	Rego Expiry:	19 Aug 2026
WoF Expiry:	18 Apr 2026	Odometer:	135,293 Kms
Good No.:	27149442	VIN:	7AT0H64BX18234714
Next Service:	145,000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle habeen driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

ncy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor Stone Chips Windscreen

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Km
Inspected by:	Darren Beban	
Published by:	James Scott	
Inspection Date:	29 Oct 2025	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tinx{\ti}\xitit\}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texitit}\xititt{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\til\tinit}\\ \text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\texi}\tilit{\titt{\text{\tinit}\\ \tittt{\text{\text{\text{\text{\ti}\tittt{\til\titt{\text{\text{\text{\text{\texi}\tittit{\text{\til\tittil\titt{\tittil\til\titt{\text{\texi}\tittt{\text{\texi}\tittit{\texi}\tilitt{\tii}\tittt{\tii}\tittitt{\tii}\tii}		
Radiator / Hoses (visual)	/		
Transmission		l	
Operation	V		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake			
Tyres (lowest observed tread d	epth of	tvres)	
Left front			6.5 mm
Right front		7	7.0 mm
Left rear			7.0 mm
Right rear			7.5 mm
Spare	Yes	<u> </u>	
Suspension			
Suspension performance			
Steering performance	· ·		
Shock absorbers			
Air Conditioning / Heater	•		
Operation			
Electrical / Accessories	•		
Head lights	V		
Tail lights	~		
Indicators	~		
Dashboard warning lights	✓		
Wipers (front & rear)	·		
Window winder FL			
Window winder FR	~		
Window winder RL	~		
Window winder RR			
Rear view mirrors			
Radio (basic test only)			
CD (basic test only)	~		
Number of keys	2	I	L
· · · · · · · · · · · · · · · · · · ·			
Central locking	4		
Remote locking			
Sat. nav. (basic test only)			<u> </u>
Reversing camera			

I have read and understood this condition guide:

NAME

SIGNATURE