

•	Report ID:	27,149,875	Version:	1
	Created:	03 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	<b>V</b>		
Noise	V		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	<b>/</b>		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes	ı		
Performance	/		
Hand brake			
Tyres (lowest observed tread d	lepth of	tyres)	
Left front			1.0 mm
Right front			1.0 mm
Left rear			5.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension	l		
Suspension performance	1		
Steering performance	~		
Shock absorbers	1		
Air Conditioning / Heater		1	
Operation	1		
Electrical / Accessories			
Head lights	~		
Tail lights	1		
Indicators	1		
Dashboard warning lights	/		
Wipers (front & rear)	1		
Window winder FL	/		
Window winder FR	/		
Window winder RL	<b>/</b>		
Window winder RR	<b>/</b>		
Rear view mirrors	/	<u> </u>	
Radio (basic test only)	1		
CD (basic test only)			
Number of keys	2	ı	
Central locking	_		
Remote locking	1	<del> </del>	
Sat. nav. (basic test only)	+	-	
Reversing camera		-	
neversing Carriera			

Make:	Toyota	Model:	Corolla
Body Style:	Hatchback	Year:	2006
Rego No.:	DGM444	Rego Expiry:	08 Mar 2026
WoF Expiry:	09 Oct 2026	Odometer:	109,644 Kms
Good No.:	27149875	VIN:	JTDKR22E600248160
Next Service:	119,000 km	Service History:	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key \* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Windscreen chip in cva.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Freshly serviced.

New battery installed.

Front wheel drive.

Interior Comn	nents		
Seats:	Good		
Carpets:	Average		
Panels:	Good		
Dashboard:	Good		
General Comr	General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Imraan Bryant	
Published by:	Erin White	
Inspection Date:	29 Oct 2025	

I have	read	and	understo	ood
this co	nditi	on a	uide	

NAME			