

# **Basic Condition Guide**

Report ID:	27,150,092	Version:	3
Created:	06 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission		•	
Operation	V		
Noise	/		
Clutch			1
CV joints	V		
Wheel bearings	1		
Brakes			
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	<u> </u>
Left front			3.8 mr
Right front			3.8 mr
Left rear			4.4 mr
Right rear			1.7 mr
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	V		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories		1	
Head lights	V		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	/		
Window winder FR	V		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	2		
Central locking	·	1	
Remote locking	1		
Sat. nav. (basic test only)			1
Reversing camera	·		<u> </u>
g carriera	Ť	<u> </u>	


Make:	Mazda	Model:	CX-5
Body Style:	SUV	Year:	2021
Rego No.:	NJY694	Rego Expiry:	23 Mar 2026
WoF Expiry:	17 Nov 2026	Odometer:	114,119 Kms
Good No.:	27150092	VIN:	JM0KF2W7A00665713
Next Service:	122,000 Kms	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Kev

,				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

# **Body Inspection Comments**

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

# Interior Comments Seats: Average Carpets: Average Panels: Average Dashboard: Average

## **General Comments**

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Chris McQuade		
Published by: Nitiphum Yordsiri			
Inspection Date:	ion Date: 03 Nov 2025		

I have read and understood this condition guide:

NAME

SIGNATURE