

Report ID: 27,150,636		Version:	1
Created:	01 Nov 2025		

		Posi	c Condition Guide	Report ID: 27,
	nue	5 <u>Basi</u>	C Condition Guide	Created: 01
Make:	Subaru	Model:	Impreza	
Body Style:	Sedan	Year:	2015	Facility
Rego No.:	PTQ573	Rego Expiry:	18 Apr 2026	Engine
WoF Expiry:	17 Oct 2026	Odometer:	108,053 Kms	Oil level
Good No.:	27150636	VIN:	7AT0GF09X21008269	Smoke & fumes
Next Service:	118034	Service History:	No	Engine perform
Note: This report is	not a warranty	,		Noise
This report is a guide	e only. Consideration is mad	le for age and mileage. I	Parts have not been dismantled or 'h from cold. The Vendor recommends a	Coolant condition
	ection prior to purchase an			Cooling perforn
Key				Radiator / Hoses
S = Scratch R	= Rust $C = C$	rack * = Deca	ls W = Significant scuffs	Transmission
D = Dent P	T = Paint defect P = Paint defect	in dent SC = Stor	ne Chips	Operation
				Noise
				Clutch
	\ <u>\</u>			CV joints
				Wheel bearings
S SC	Brakes			
				Performance
				Hand brake
D SC	18			Tyres (lowest of
				Left front
			S	Right front
				Left rear
				Right rear
Note: some defects	and blemishes may not be	displayed in the diagra	ım	Spare
Body Inspecti	on Comments			Suspension
				Suspension per
				Steering perform
				Shock absorber
Conditions Dur	ring Body Inspection		Dry	Air Conditionir
Under Carriag	je and Under Bonnet	Inspection Comm	ents	Operation
Front wheel driv				Electrical / Acco
				Head lights
				Tail lights
Interior Comm	nents			Indicators
Seats:	Good			Dashboard wari
	1			_ asoura war

		Requires	
	OK	Attention	N/A
Engine			ī
Oil level	<i>'</i>		
Smoke & fumes	\(\tau \)		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission	l .		
Operation	/		
Noise	~		
Clutch			_
CV joints	~		
Wheel bearings	/		<u> </u>
Brakes			
Performance	/		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			4.9 mm
Right front			4.5 mm
Left rear		4	4.3 mm
Right rear		5	5.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	1		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			~
Number of keys	1		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)			~

Road Conditions During Test Drive			
Engine Timing Mechanism			
Evidence of Cam Belt Replacement		No	Kms
meron Senior-A	Arnold		
uart Phillips			
Oct 2025			
	hanism It Replacement Imeron Senior-A uart Phillips	hanism Timing Chain It Replacement Yes Imeron Senior-Arnold Uart Phillips	hanism Timing Chain It Replacement Yes No Imeron Senior-Arnold uart Phillips

I have read and understood this condition guide:

Good Good

Good

Carpets:

Panels:

Dashboard:

General Comments

NAME SIGNATURE