

•	Report ID: 27,150,810		Version:	2
	Created:	18 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	<b>V</b>		
Smoke & fumes	<b>/</b>		
Engine performance	V		
Noise	<b>✓</b>		
Coolant condition	<b>/</b>		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	<b>/</b>		
Noise	/		
Clutch			~
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	1		
Hand brake	1		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		-	7.0 mm
Right front		į	5.0 mm
Left rear		ţ	5.0 mm
Right rear		(	6.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>✓</b>		
Electrical / Accessories			
Head lights	/		
Tail lights	<b>✓</b>		
Indicators	<b>✓</b>		
Dashboard warning lights			
14.0 (6	<b>✓</b>		
Wipers (front & rear)	<i>'</i>		
Wipers (front & rear) Window winder FL			
	<b>/</b>		
Window winder FL	\( \sqrt{\sq}}}}}}\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}		
Window winder FL Window winder FR	V V		
Window winder FL Window winder FR Window winder RL	\( \sqrt{\sq}}}}}}\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}		
Window winder FL Window winder FR Window winder RL Window winder RR	\( \sigma \)		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	V V V V		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	V V V V V		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V V		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	\( \frac{1}{\sqrt{2}} \)		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\( \frac{1}{\sqrt{2}} \)		


Make:	Volkswagen	Model:	Jetta
Body Style:	Sedan	Year:	2007
Rego No.:	PDG692	Rego Expiry:	11 Feb 2026
WoF Expiry:	02 Dec 2026	Odometer:	57,921 Kms
Good No.:	27150810	VIN:	WVWZZZ1KZ7M047802
Next Service:	76,400 km	Service History:	No

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Windscreen edges slight delaminating.

L/H wing mirror glass slightly ajar.

Conditions During Body Inspection	Wet		
Under Carriage and Under Bonnet Inspection Comments			

Freshly serviced.

Front wheel drive.

Interior Comments	
Seats:	Average
Carpets:	Average
Panels:	Poor
Dashboard:	Average
General Comments	

New VTNZ warrant of fitness.

Road Conditions During Test Drive		Wet		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	<b>V</b> No	Kms
Inspected by:	Imraan Bryant			
Published by:	Erin White			
Inspection Date:	28 Oct 2025			

I have read and understood
this condition guide:

NAME			