

•	Report ID:	27,151,161	Version:	1
	Created:	27 Nov 2025		

U	nuei	S Basi	C Condition Guide	Created: 2	27 Nov 2025			
Make:	Nissan	Model:	Note			Requires		
Body Style:	Hatchback	Year:	2014	- Engine		K Attention	n N/A	
Rego No.:			25 Jul 2026	_		,	1	
WoF Expiry:			Oil level  Smoke & fumes			+		
Good No.:	27151161	VIN:	7AT0DH79X23204041	Smoke & fumes Engine performance			-	
Next Service:	112,000 km	Service History:	No	Noise	ormance /			
Note: This report is	not a warranty	Coolant cond	-		+			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a							-	
full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling perf		.	-	
Key				Radiator / Ho	, ,			
	= Rust C = C		3	Transmissio		,	<u> </u>	
D = Dent P	$\Gamma = Paint defect  P = P$	Pin dent SC = Sto	ne Cnips	Operation	•			
	W	S SC S R SC	PT S	Noise			<u> </u>	
				Clutch			-	
	$\sim$			CV joints	•			
SPT				Wheel bearing	ngs 🗸			
$\neg \neg P$	18			Brakes		.	_	
1				Performance				
				Hand brake	· ·			
PT SC				Tyres (lowest observed tread depth of tyres)				
				Left front				
				Right front		5.0 mm		
S	W	Left rear		6.0 mm				
	VV	P SC S SC	W	Right rear		6.0 mm		
	and blemishes may not be	e displayed in the diagra	ım	Spare	Y	es		
Body Inspecti	on Comments			Suspension				
				Suspension	performance 🗸	<b>′</b>		
				Steering per	formance 🗸	<u>'</u>		
				Shock absor	bers 🗸	<u> </u>		
Conditions During Body Inspection Dry			Air Conditio	ning / Heater		_		
Under Carriag	e and Under Bonnet	t Inspection Comm	nents	Operation	•	<u> </u>		
Freshly serviced				Electrical / Accessories				
Front wheel drive.					•	<b>'</b>		
				Tail lights	•	<u>'</u>		
Interior Comments					V	<b>,</b>		
Seats:	Good			Dashboard v	varning lights 🗸	<b>,</b>		
Carpets:	arpets: Good			Wipers (fron	t & rear)	<i>'</i>		
Panels: Good			Window win	der FL 🗸	<b>,</b>			
Dashboard: Good			Window win	der FR 🗸	,	1		
General Comments				Window win	der RL 🗸	,		
New VTNZ warrant of fitness.					der RR 🗸	,	1	
				Rear view m	irrors	,		
				Padio (basic	tost only)	,	1	

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Imraan Bryant			
Published by:	Erin White			
Inspection Date:	30 Oct 2025			

I have read and understood		
this condition quide	NAME	CICNATURE

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1 2

•

•