

Basic Condition Guide


•	Report ID: 27,151,212		Version:	2
	Created:	16 Dec 2025		

	OK	Requires Attention	N/A
Engine	<u> </u>		,,
Oil level	V		1
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	'		1
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes		l	
Performance	/		
Hand brake	1		
Tyres (lowest observed tread	depth of	tyres)	I
Left front	Ī		1.0 mm
Right front			5.0 mm
Left rear			7.0 mm
Right rear		-	7.0 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	/		
Tail lights	'		
Indicators	'		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	'		
Window winder FR	•		
Window winder RL	/		
Window winder RR	'		
Rear view mirrors	'		
Radio (basic test only)	•		
CD (basic test only)	'		
Number of keys	1		
Central locking	•		
Remote locking	1		
Sat. nav. (basic test only)			1
Reversing camera			V

		<u> </u>		
Make:	Toyota	Model:	Corolla	
Body Style:	Hatchback	Year:	2004	
Rego No.:	CHH695	Rego Expiry:	26 Apr 2026	
WoF Expiry:	24 Dec 2026	Odometer:	146,970 Kms	
Good No.:	27151212	VIN:	JTDKR22E702028093	
Next Service:	156,000 km	Service History:	No	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				

Key

S = Scratch* = DecalsW = Significant scuffs R = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

R/R tail light has hair line cracks.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Freshly serviced.

New front brake pads and rotors installed.

Front wheel drive.

Interior Comments	
Seats:	Average
Carpets:	Good
Panels:	Poor
Dashboard:	Good
General Comments	

New VTNZ warrant of fitness.

Interior parcel tray lid damaged.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Imraan Bryant	
Published by:	Erin White	
Inspection Date:	29 Oct 2025	

I have read and understood
this condition guide:

NAME			