

## **Basic Condition Guide**


| Report ID: | 27,151,310  | Version: | 2 |
|------------|-------------|----------|---|
| Created:   | 06 Nov 2025 |          |   |

|                                     |   | Kona   |  |  |  |
|-------------------------------------|---|--|--|--|--|
| SUV                                 | Year:   | 2022   |  |  |  |
| PNR892                              | Rego Expiry:  | 19 Jan 2026  |  |  |  |
| 21 Oct 2026                         | Odometer:   | 34,238 Kms   |  |  |  |
| 27151310                            | VIN:  | KMHK281GUNU165404  |  |  |  |
| 38400                               | Service History:  | Yes  |  |  |  |
| Note: This report is not a warranty |   |  |  |  |  |
| 1                                   | PNR892<br>21 Oct 2026<br>27151310<br>38400<br>ot a warranty | PNR892 Rego Expiry: 21 Oct 2026 Odometer: 27151310 VIN: 38400 Service History: ot a warranty nly. Consideration is made for age and mileage. P |  |  |  |

full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = ScratchR = RustC = Crack\* = DecalsW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Dry Conditions During Body Inspection **Under Carriage and Under Bonnet Inspection Comments** 

## **Interior Comments** Seats: Good Carpets: Good Good Panels: Dashboard:

## **General Comments**

Partial service history

Equipped with Both Domestic Home & Commercial Charging Cables

| Road Conditions During Test Drive |                | Dry     |    |     |
|-----------------------------------|----------------|---------|----|-----|
| Engine Timing Mechanism           |                | Unknown |    |     |
| Evidence of Cam Belt Replacement  |                | Yes     | No | Kms |
| Inspected by:                     | Sione Mae      |         |    |     |
| Published by:                     | Bruce Screaton |         |    |     |
| Inspection Date:                  | 29 Oct 2025    |         |    |     |

|                                | ОК       | Requires<br>Attention | N/A      |
|--------------------------------|----------|-----------------------|----------|
| Engine                         |          |                       |          |
| Oil level                      |          |                       | V        |
| Smoke & fumes                  |          |                       | ~        |
| Engine performance             | <b>✓</b> |                       |          |
| Noise                          | <b>/</b> |                       |          |
| Coolant condition              | <b>/</b> |                       |          |
| Cooling performance            | V<br>V   |                       |          |
| Radiator / Hoses (visual)      | <b>/</b> |                       |          |
| Transmission                   |          |                       |          |
| Operation                      | <b>/</b> |                       |          |
| Noise                          | <b>/</b> |                       |          |
| Clutch                         |          |                       | ~        |
| CV joints                      | <b>/</b> |                       |          |
| Wheel bearings                 | /        |                       |          |
| Brakes                         |          |                       |          |
| Performance                    | /        |                       |          |
| Hand brake                     | <b>/</b> |                       |          |
| Tyres (lowest observed tread d | epth of  | tyres)                |          |
| Left front                     |          | 3                     | 3.0 mm   |
| Right front                    |          | 4                     | 1.0 mm   |
| Left rear                      |          | (                     | 6.0 mm   |
| Right rear                     |          | (                     | 6.0 mm   |
| Spare                          | N/A      |                       |          |
| Suspension                     |          |                       |          |
| Suspension performance         | <b>✓</b> |                       |          |
| Steering performance           | ~        |                       |          |
| Shock absorbers                | ~        |                       |          |
| Air Conditioning / Heater      |          |                       |          |
| Operation                      | /        |                       |          |
| Electrical / Accessories       |          |                       |          |
| Head lights                    | /        |                       |          |
| Tail lights                    | /        |                       |          |
| Indicators                     | <b>✓</b> |                       |          |
| Dashboard warning lights       | <b>✓</b> |                       |          |
| Wipers (front & rear)          | <b>✓</b> |                       |          |
| Window winder FL               | <b>✓</b> |                       |          |
| Window winder FR               | <b>/</b> |                       |          |
| Window winder RL               | /        |                       |          |
| Window winder RR               | /        |                       |          |
| Rear view mirrors              | <b>✓</b> |                       |          |
| Radio (basic test only)        | /        |                       |          |
| CD (basic test only)           | •        |                       |          |
| Number of keys                 | 2        |                       |          |
| Central locking                | /        |                       |          |
| Remote locking                 | /        |                       |          |
| Sat. nav. (basic test only)    |          |                       | <b>'</b> |
| Reversing camera               | <b>/</b> |                       |          |
|                                |          |                       |          |

I have read and understood this condition guide:

NAME