

# **Basic Condition Guide**

•	Report ID:	27,151,470	Version:	1
	Created:	08 Nov 2025		

	OK	Requires Attention	N/A
Engine		Accidon	14/7
Oil level	V		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	V		
Noise	1		
Clutch			~
CV joints	V		
Wheel bearings	<b>'</b>		
Brakes			
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread of	depth of	tyres)	
Left front			4.0 mm
Right front			4.0 mm
Left rear		(	6.0 mm
Right rear			6.0 mm
Spare	Yes		
Suspension		1	
Suspension performance	/		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater		T T	ı
Operation	<b>/</b>		
Electrical / Accessories		ı	ĭ
Head lights	/		
Tail lights	~		
Indicators	<b>/</b>		
Dashboard warning lights	<b>/</b>		
Wipers (front & rear)	<b>/</b>		
Window winder FL	<b>/</b>		
Window winder FR	V		
Window winder RL	V		
Window winder RR	V		
Rear view mirrors	<i>V</i>		
Radio (basic test only)	<b>V</b>		
CD (basic test only)	1		
Number of keys	1	1	ı
Central locking	/		
Remote locking			
Sat. nav. (basic test only)	<b>,</b>		


Make:	KIA	Model:	Sportage
Body Style:	suv	Year:	2018
Rego No.:	QAR460	Rego Expiry:	08 May 2026
WoF Expiry:	08 Aug 2026	Odometer:	199,072 Kms
Good No.:	27151470	VIN:	KNAPN81CSJ7458340
Next Service:	209,000 km	Service History:	No

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Kev

ncy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Slight surface rust spot on L/F corner of top of windscreen. Minor pitting in windscreen.

Conditions During Body Inspection	Dry	

## **Under Carriage and Under Bonnet Inspection Comments**

4WD

Oxidation on front bumper reinforcing.

Freshly serviced.

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive		Wet
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Imraan Bryant	
Published by:	Erin White	

I have read and understood this condition guide:

Inspection Date: 28 Oct 2025

Reversing camera