


Report ID:	27,152,342	Version:	1
Created:	11 Nov 2025		

Make:	Hyundai	Model:	Imax
Body Style:	People Mover	Year:	2020
Rego No.:	NEK293	Rego Expiry:	29 May 2026
WoF Expiry:	04 Nov 2026	Odometer:	129,486 Kms
Good No.:	27152342	VIN:	KMHWH81KMLU131633
Next Service:	140000	Service History:	No

diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

# Key

W = Significant scuffs S = ScratchR = RustC = Crack\* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

# **Body Inspection Comments**

Conditions During Body Inspection	Wet		
Haday Camia na and Haday Dannat has a stirry Carray anta			

## **Under Carriage and Under Bonnet Inspection Comments**

Interior Comments	
Seats:	stained
Carpets:	Average
Panels:	Average
Dashboard:	Average

### **General Comments**

Road Conditions During Test Drive		Wet	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No	Kms
Inspected by:	Greg Morgan		
Published by:	Bailey Seymour		
Inspection Date:	28 Oct 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	<b>✓</b>		
Smoke & fumes	<b>/</b>		
Engine performance	<b>✓</b>		
Noise	\( \frac{1}{V} \)		
Coolant condition	~		
Cooling performance	<b>V</b>		
Radiator / Hoses (visual)	<b>V</b>		
Transmission			
Operation	/		
Noise	/		
Clutch			<b>'</b>
CV joints			<b>/</b>
Wheel bearings	<b>/</b>		
Brakes			
Performance	<b>/</b>		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			5.0 mm
Right front			5.0 mm
Left rear			1.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension		1	
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		ı	
Operation	/		
Electrical / Accessories		ı	
Head lights	/		
Tail lights	<b>/</b>		
Indicators	V		
Dashboard warning lights	<b>✓</b>		
Wipers (front & rear)	<b>V</b>		
Window winder FL	<b>V</b>		
Window winder FR	/		
Window winder RL			
Window winder RR			
Rear view mirrors	/		
Radio (basic test only)	•		
CD (basic test only)	1		
Number of keys	-	Γ	
Central locking	<i>/</i>		
Remote locking	•		
Sat. nav. (basic test only)	.1		_ <b>-</b>
Reversing camera			

I have read and understood this condition guide:

NAME