

•	Report ID:	27,152,632	Version:	1
	Created:	26 Nov 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	1		
Engine performance	1		
Noise	V		
Coolant condition	1		
Cooling performance	V		
Radiator / Hoses (visual)	1		
Transmission			
Operation	V		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes		1	
Performance	<b>V</b>		
Hand brake	- V		
Tyres (lowest observed tread of	lonth of	turos)	
Left front	Геригог		1.0 mm
Right front			5.0 mm
Left rear			7 mm
Right rear	.,		7 mm
Spare	Yes		
Suspension		1	
Suspension performance	/		
Steering performance	/	-	
Shock absorbers	/		
Air Conditioning / Heater	1	<u> </u>	
Operation	/		
Electrical / Accessories			
Head lights		<b>/</b>	
Tail lights	<b>/</b>		
Indicators	•		
Dashboard warning lights	<b>/</b>		
Wipers (front & rear)	V		
Window winder FL			
Window winder FR	~		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1		
Number of keys	1	1	
Central locking			
Remote locking	1	1	
Sat. nav. (basic test only)		1	
Reversing camera		1	
		I	

Make:	Nissan	Model:	Note
Body Style:	Hatchback	Year:	2006
Rego No.:	KST138	Rego Expiry:	29 Jun 2026
WoF Expiry:	28 Aug 2026	Odometer:	152,945 Kms
Good No.:	27152632	VIN:	7AT0DH79X17149164
Next Service:		Service History:	No

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Headlights faded. Lhs mirror scuffed

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

# **General Comments**

Air conditioning and heating systems ok.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Anna Zandstra	
Inspection Date:	30 Oct 2025	

I have read and understood
this condition guide:

NAME			