

Report ID:	27,153,171	Version:	2
Created:	11 Nov 2025		

Make:	Subaru	Model:	XV		
Body Style:	Hatchback	Year:	2017		
Rego No.:	PRK893	Rego Expiry:	16 Aug 2026		
WoF Expiry:	25 Nov 2026	Odometer:	160,691 Kms		
Good No.:	27153171	VIN:	7AT0GF1XX22035730		
Next Service:	170700	Service History:	No		
his report is a gui liagnostic testing ull mechanical ins		een driven up to 50km/	Parts have not been dismantled or 'h from cold. The Vendor recommends a or an additional charge. -		
Key	D Dt	·	l- W C::f:tff-		
	R = Rust $C = CPT = Paint defect$ $P = P$				
sc		S P SC			
			S		
0.00	MA WI	+			
s sc					
	HMI II				
D SC			NL HIR		
	The same of the sa	+			
		sc			
	s and blemishes may not be	displayed in the diagra	nm		
Body Inspec	tion Comments				
•					
			I D		
	uring Body Inspection		Dry		
Under Carria	ge and Under Bonnet	Inspection Comm	ents		
Interior Co					
Interior Com					
Seats:					
Carpets: Average					

	01/	Requires	N1/A
Fueine	OK	Attention	N/A
Engine			1
Oil level	/		
Smoke & fumes	V		
Engine performance	/		
Noise	1		
Coolant condition	~		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			<u> </u>
Operation	-		
Noise	/		
Clutch			-
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	V		
Tyres (lowest observed tread	depth of	tyres)	
Left front		8	3.0 mm
Right front		{	3.0 mm
Left rear			5.0 mm
Right rear		į	5.0 mm
Spare	N/A		
Suspension			
Suspension performance	1		
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			•
Head lights	~		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	V		
Window winder FL	V		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	1	I	
Central locking	1	1	
Remote locking	1		
Sat. nav. (basic test only)			J
	1		
Reversing camera		ļ	ļ

Road Condition	s During Test Drive	Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Chris Buckley		
Published by: Jeremy Hutchings		s	
Inspection Date:	Inspection Date: 29 Oct 2025		

I have read and understood this condition guide:

Good

Good

Panels:

Dashboard:

General Comments