

Basic Condition Guida

Report ID:	27,154,202	Version:	2
Created:	30 Dec 2025		

	umer	S	C Condition Guide	Created:	30 Dec 2025			
Make:	Holden	Model:	Captiva 7				Requires	
Body Style:	SUV	Year:	2017			OK	Attention	N/A
Rego No.:	KSJ284	Rego Expiry:	25 May 2026	Engine				
WoF Expiry:	08 Nov 2025	Odometer:	183,934 Kms	Oil level		/		
Good No.:	27154202	VIN:	KL3CA2669HB741278	Smoke & fu		✓		
Next Service:	190,416km	Service History:	Yes	Engine per	formance	/		
Note: This report is		Service History.	1.00	Noise		/		
his report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant co	ndition	✓		
	iagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.				rformance	/		
√ey				Radiator / I	Hoses (visual)	/		
•	= Rust $C = C$	irack *= Deca	ls W = Significant scuffs	Transmiss	ion			
D = Dent $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$			Operation		>			
	W		WP	Noise		>		
W D D W P			Clutch				1	
S				CV joints		V		
				Wheel bea	rings	/		
				Brakes				
DR DR				Performan	ce	/		
				Hand brak	e	/		
				Tyres (lowest observed tread depth of tyres)				
$$ \emptyset				Left front		4.0 mm		
				Right front	:	6.0 mr		
				Left rear			6	6.0 mm
D	S	P D	S	Right rear			6	3.0 mn
Note: some defects and blemishes may not be displayed in the diagram			Spare		Yes			
Body Inspection		. displayed in the diagra		Suspension				
, ,		oor seal torn. Rear	wipers split. RR seat release	•	n performance	1		
lever damaged.	LR tyre outer edge s	scalloped.		•	erformance	V		
				Shock abso		/		
Conditions During Body Inspection Dry				Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments .				Operation	g, meater	/		
				•	/ Accessories	-		
				Head light		/		
				_	3			
				Tail lights				I

Interior Comments Seats: Good Good Carpets: Good Panels: Good Dashboard:

General Comments

Battery tested- cell bad needs replacing. Windscreen crack out of cva. Engine light comes on.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Sharnae Smith	
Published by:	Henry Manders	
Inspection Date:	28 Nov 2025	

I have read and understood
this condition quide

NAME		

SIGNATURE		

1

1

1

1

1

1

1 1

Indicators

Dashboard warning lights

Wipers (front & rear)

Window winder FL

Window winder FR

Window winder RL

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera