


Report ID: 27,154,890		Version:	3
Created:	04 Nov 2025		

Make:	Mini	Model:	Countryman
Body Style:	SUV	Year:	2018
Rego No.:	LEM93	Rego Expiry:	15 Jun 2026
WoF Expiry:	14 Nov 2026	Odometer:	91,238 Kms
Good No.:	27154890	VIN:	WMWYS320803E54135
Next Service:	101243	Service History:	No

diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

,				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor stone chips on windscreen

Conditions During Body Inspection	Dry		
Under Carriage and Under Ronnet Inspection Comments			

Front wheel drive

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Cameron Senior-A	Arnold
Published by:	Jaykib Collins	
Inspection Date:	29 Oct 2025	

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	✓		
Engine performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tinit}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinit}\xi{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\tint{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\text{\text{\text{\text{\text{\tin}\tint{\text{\tin}\tint{\text{\text{\texi}\text{\text{\text{\text{\text{\texi}\text{\tex{\text{\texi}\tint{\text{\texi}\tint{\text{\texi}\tinz}\tinz}\tex{\text{\texi}\tint{\texi}\tinz{\text{\texi}\texi{\texi{\ti		
Noise	~		
Coolant condition	✓		
Cooling performance	~		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	/		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	/		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			1.5 mm
Right front			5 mm
Left rear			4 mm
Right rear		4	1.0 mm
Spare	No		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	~		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	/		
Window winder FR	✓		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			/
Number of keys	2		
Central locking	✓		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	/		

I have read and understood this condition guide:

NAME

SIGNATURE