

Report ID:	27,155,120	Version:	3
Created:	03 Nov 2025		

	OK	Requires Attention	N/A
Engine		7100011011	,,, .
Oil level	V		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			l
Operation	V		1
Noise	1		
Clutch			1
CV joints	/		
Wheel bearings	1		
Brakes			<u> </u>
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	denth of	l tvres)	l
Left front			3.0 mr
Right front			6.0 mr
Left rear			3.0 mr
Right rear			3.0 mr
Spare	Yes		J.O 1111
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V	1	
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	· /		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			1
Number of keys	2	l .	
Central locking	- V	1	
Remote locking	1		
Sat. nav. (basic test only)	1		
Reversing camera	1		
neversing carriera		<u> </u>	


Make:	KIA	Model:	Cerato
Body Style:	Hatchback	Year:	2022
Rego No.:	PNH940	Rego Expiry:	24 Apr 2026
WoF Expiry:	23 Oct 2026	Odometer:	39,172 Kms
Good No.:	27155120	VIN:	KNAF4517VN5151598
Next Service:	49,183 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

,				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Chipped windscreen.

Conditions During Body Inspection	Dry	
Under Carriage and Under Bonnet Inspection Comments		

Interior Comments		
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Daryll Timms	
Published by:	Shane Charlton	
Inspection Date:	30 Oct 2025	

I have read and understood this condition guide:

NAME

SIGNATURE