

Report ID:	27,155,804	Version:	3
Created:	07 Nov 2025		


Make:	BMW	Model:	1181
Body Style:	Hatchback	Year:	2016
Rego No.:	NWU540	Rego Expiry:	25 May 2026
WoF Expiry:	19 Nov 2026	Odometer:	121,063 Kms
Good No.:	27155804	VIN:	WBA1R520X05C72076
Next Service:	131000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = ScratchR = RustC = Crack* = DecalsW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Under Carriage and Under Bonnet Inspection Comm	nents
Conditions During Body Inspection	Dry

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
General Comments		

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kn	ns
Inspected by:	Greg Morgan		
Published by:	Bailey Seymour		
Inspection Date:	30 Oct 2025		

	OK	Requires Attention	
Engine			
Oil level	1		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	V		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			'
CV joints	1		
Wheel bearings	/		
Brakes			
Performance	V		
Hand brake	/		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	ори о.		7.0 mm
Right front			7.0 mm
Left rear			7.0 mm
Right rear			7.0 mm
Spare	N/A		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	/	1	
Tail lights	<i>\sqrt{\sq}}}}}}}}}}}}}} \sqite\septionup\sign{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}} \sqrt{\sq}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}} \sqrt{\sqrt{\sqrt{\sq}}}}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt</i>		
Indicators	<i>-</i>		
Dashboard warning lights	V		
Wipers (front & rear)	V		
Window winder FL	V		
Window winder FR	V		
Window winder RL			
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			
Number of keys	2	<u> </u>	
Central locking	· ·	1	
Remote locking	V		
	<i>J</i>		
Sat. nav. (basic test only) Reversing camera			
neversing carriera		<u> </u>	

I have read and understood this condition guide:

NAME