

•	Report ID:	27,157,416	Version:	3
	Created:	21 Nov 2025		

	Requi	
Frantis	OK Attent	tion N/A
Engine		
Oil level	/	
Smoke & fumes	<i>'</i>	
Engine performance	<i>V</i>	
Noise	•	
Coolant condition	•	
Cooling performance	•	
Radiator / Hoses (visua	il) 🗸	
cant scuffs Transmission		
Operation	V	
PT Noise	· ·	
Clutch		/
S CV joints	· ·	
Wheel bearings	✓	
Brakes		
Performance	V	
SC Hand brake	V	
Tyres (lowest observe	d tread depth of tyres)	
Left front		5.0 mr
P Right front		5.0 mr
Left rear		3.0 mn
PT Right rear		3.0 mn
Spare	Yes	
Suspension		
Suspension performan	nce 🗸	
Steering performance	V	
Shock absorbers	V	
Air Conditioning / He		
Operation	✓	1
Electrical / Accessorie		
Head lights	-s	I
	<i>'</i>	
Tail lights Indicators	·	
Dashboard warning lig		
Wipers (front & rear)	<i>\\</i>	
Window winder FL	<i>'</i>	
Window winder FR	•	
Window winder RL	•	
Window winder RR	· ·	
Rear view mirrors	· ·	
Radio (basic test only)	· ·	
CD (basic test only)	V	
Number of keys	1	
Kms Central locking	· ·	
Remote locking	· ·	
Sat. nav. (basic test on	y)	V

Make:	Hyundai	Model:	lx35
Body Style:	SUV	Year:	2015
Rego No.:	JAU831	Rego Expiry:	04 Feb 2026
WoF Expiry:	17 Nov 2026	Odometer:	176,294 Kms
Good No.:	27157416	VIN:	KMHJU81VSFU007773
Next Service:	177,000	Service History:	Yes
liagnostic testing un	only. Consideration is made	een driven up to 50km/h	orts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
	= Rust C = C = Paint defect P = Pi		
SC		PT	PT
S SC PT O			SC
		PT	P
Note: some defects a	and blemishes may not be	displayed in the diagra	m
Body Inspection	on Comments		
Paint marks fror	n previous decals		
Conditions Duri	ing Body Inspection		Dry
	ing Body Inspection e and Under Bonnet	Inspection Comm	Dry
	ing Body Inspection e and Under Bonnet	Inspection Comm	-
		Inspection Comm	-
		Inspection Comm	-
	e and Under Bonnet	Inspection Comm	-
Under Carriag	e and Under Bonnet	Inspection Comm	-
Under Carriage	e and Under Bonnet		-
Under Carriage Interior Comm Seats:	e and Under Bonnet ents Average		-

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Timing Chain		
Evidence of Can	n Belt Replacement	Yes	No	Kms
Inspected by:	Finlay Lemmens			
Published by:	Anna Zandstra			
Inspection Date:	03 Nov 2025			

I have read and understood this condition guide:

General Comments

NAME _

SIGNATURE