

Basic Condition Guide

Report ID:	27,157,831	Version:	3	
Created:	12 Nov 2025			

	ullei			Created:	12 Nov 2025				
Make:	Peugeot	Model:	3008				Requires		
Body Style:	SUV	Year:	2018			OK	Attention	N/A	
Rego No.:	LMQ24	Rego Expiry:	10 May 2026	Engine					
WoF Expiry:	24 Jul 2026	Odometer:	40,557 Kms	Oil level		<i>\</i>			
Good No.: 27157831		VIN:	VF3MJAHWWJS152319	Smoke & fumes		<i>\</i>			
Next Service: 50558kms		Service History:	Yes	Engine performance		/			
Note: This report is		Service History.	Noise		✓				
This report is a guide	e only. Consideration is made	Coolant condition		✓					
diagnostic testing u full mechanical insp	ndertaken. The vehicle ha k ection prior to purchase an	oeen driven up to 50km, nd this can be arranged f	Cooling performance		✓				
Key					Hoses (visual)	✓			
S = Scratch R	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion				
D = Dent P	T = Paint defect P = P	Pin dent SC = Sto	ne Chips	Operation		✓			
		PP		Noise		/			
	$\overline{}$	\top		Clutch				~	
	(M)-			CV joints		✓			
				Wheel bea	rings	/			
				Brakes					
				Performan	ce	/			
				Hand brak	e	/			
				Tyres (lowest observed tread depth of tyres)					
				Left front			7	7.0 mm	
				Right front			6	6.5 mm	
				Left rear		3.0 mm			
		Right rear		3.0 mm					
Note: some defects	and blemishes may not be	e displayed in the diagra	ım	Spare		Yes			
Body Inspecti	on Comments			Suspension	on				
				Suspensio	n performance	/			
				Steering p	erformance	/			
				Shock abs	orbers	/			
Conditions Du	ring Body Inspection		Air Conditioning / Heater						
Under Carriag	ge and Under Bonnet	t Inspection Comm	nents	Operation		/			
				Electrical	/ Accessories				
				Head light	S	✓			
				Tail lights		✓			
Interior Comn	nents			Indicators		/			
Seats:	Good			Dashboard warning lights		/			
Carpets:	Good			Wipers (fro	ont & rear)	✓			
Panels: Good				Window w	inder FL	/			
Dashboard:	Good		Window w	inder FR	✓				
General Comr	ments	Window w	inder RL	✓					
				Window w	inder RR	/			
				Rear view	mirrors	/			
				Radio (bas	ic test only)	/			
Road Condition	ns During Test Drive	Dry		CD (basic t				1	
Engine Timing		Timing Chain		Number of keys 2					
Evidence of Cam Belt Replacement Yes			No Kms	Central loc	-	/			
Inspected by:	LukaAjitvan Woei			Remote lo		/			
1	,				3				

I have read and understood this condition guide:

Inspection Date: 01 Nov 2025

Harry Dodds

Published by:

NAME SIGNATURE

Sat. nav. (basic test only)

Reversing camera