

Basic Condition Guide

Report ID:	27,157,934	Version:	1	
Created:	24 Nov 2025			

ca II	ntuet	B asi	c Condition Guide	Crastad	24 Nov 2025				
				Created:	24 NOV 2025				
Make:	Ford	Model:	Mondeo			ОК	Requires Attention	NI/A	
Body Style:	Hatchback	Year:	2015	Engine		OK	Attention	N/A	
Rego No.:	JCR292	Rego Expiry:		Oil level		V			
WoF Expiry:	30 Oct 2026	Odometer:	139,982 Kms	Smoke & fumes		1			
Good No.:	27157934	VIN:	WF0EXXGBBEES36212			1			
Next Service:		Service History:	No	g p =		V			
lote: This report i	•	Coolant condition		1					
his report is a guid liagnostic testing u	e only. Consideration is mad indertaken. The vehicle has b	le for age and mileage. P been driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a	Cooling per		1			
ull mechanical insp	pection prior to purchase ar	nd this can be arranged f	or an additional charge.		loses (visual)	· ·			
Key				Transmissi					
S = Scratch $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffsD = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$					Operation				
				Noise		V			
S S S S S D SC					Clutch			1	
			CV joints		· ·		<u> </u>		
	$\mathcal{O}_{\mathcal{F}}$		Wheel bearings		V				
S SC W				wheel bearings Brakes					
				Performano		·	Ι		
				Hand brake		1			
DRCSC	HOS			Tyres (lowest observed tread depth of tyres)					
D KOOG (Left front 5.0 mm					
			S D SC	Right front		6.0 mm			
					Left rear			3.0 mm	
S		D S			3.0 mr				
lote: some defects	s and blemishes may not be	a displayed in the diagr	am.	Spare		Yes			
	ion Comments	e dispiayed in the diagn	3111	Suspension	n	1			
, ,	bumper damaged Lhf	mudflap loose	-	performance	V				
		·		Steering pe	•	1			
				Shock abso		1			
Conditions Du	ıring Body Inspection		Dry		oning / Heater		L		
	ge and Under Bonne	t Inspection Comn	-	Operation	<u> </u>	V			
	9		Electrical / Accessories						
				Head lights		V			
				Tail lights		1			
Interior Comments						1			
Seats:	Average			Dashboard	warning lights	1			
Carpets:	Average		Wipers (fro		1				
Panels:				Window wi		1			
Dashboard: Average					nder FR	1			
General Com				Window wi	nder RL		~		
Both rear wind	ows operation very ter	mperamental. Lhf o	Window wi	nder RR		~			
				Rear view n	nirrors	1			
				Radio (basic	test only)	1			
Road Condition	ons During Test Drive	Dry		CD (basic test only)					
Road Conditions During Test Drive Dry				,	.,				

I have read and understood this condition guide:

Inspection Date: 31 Oct 2025

Engine Timing Mechanism

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Gary Adams

Anna Zandstra

NAME			

No

Cambelt

✓ Yes

SIGNATURE		

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

139,982 Kms

1

1