

Basic Condition Guide


Report ID:	27,157,981	Version:	1
Created:	06 Nov 2025		

Make:	Ford	Model:	Ecosport
Body Style:	SUV	Year:	2016
Rego No.:	KFA863	Rego Expiry:	18 Mar 2026
WoF Expiry:	20 Nov 2026	Odometer:	78,827 Kms
Good No.:	27157981	VIN:	MAJBXXMRKBGD27489
Next Service:	92420	Service History:	No
Note: This report is not a warranty			

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

,				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Stone chip front window screen

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments		
Seats:	wear	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

General Comments

Transmission may need attention.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	V No	Kms
Inspected by:	Melissa Wilson			
Published by:	Kris Milne			
Inspection Date:	06 Nov 2025			

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tinx{\ti}\xitit\}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texitit}\xititt{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\til\tinit}\\ \text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\texi}\tilit{\titt{\text{\tinit}\\ \tittt{\text{\text{\text{\texi}\tilit{\text{\texitilex{\text{\texi}\text{\text{\texi}\tilit{\text{\texi}\tilitt{\text{\texi}\text{\texi{\texi{\texi{\texi}\tint{\texit{\texi}\til\tint{\texitilex{\tiin}\tilitt{\texitilex{\tiin}\tiit		
Radiator / Hoses (visual)	/		
Transmission		l	
Operation	V		
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		5.0 mm
Right front		6	6.0 mm
Left rear			3.5 mm
Right rear			6.5 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance			
Shock absorbers			
Air Conditioning / Heater		l	
Operation			
Electrical / Accessories			
Head lights	V		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	·		
Window winder FL	·		
Window winder FR	·		
Window winder RL	·		
Window winder RR	· ·		
Rear view mirrors	·		
Radio (basic test only)	·		
CD (basic test only)	· ·		
Number of keys	2	I.	Ь
Central locking	- /		
Remote locking	· /		
Sat. nav. (basic test only)			
Reversing camera			

I have read and understood this condition guide:

NAME

SIGNATURE