

Report ID:	27,158,263	Version:	2
Created:	12 Nov 2025		

		Doo:	a Canalitian Cuida	Report ID:	27,158,263
	urner	S Basi	c Condition Guide	Created:	12 Nov 2025
Make:		Model:	Rav4		
	Toyota				
Body Style:		Year:	2022	Engine	
Rego No.:	PFW603	Rego Expiry:	02 May 2026	Oil level	
WoF Expiry:	02 May 2026	Odometer:	76,823 Kms	Smoke & fu	ımes
Good No.:	27158263	VIN:	JTMBW3FV00D145446	Engine per	formance
Next Service:	84,000 knskms	Service History:	Yes	Noise	
Note: This report This report is a qui	•	de for age and mileage.	Parts have not been dismantled or	Coolant co	ndition
diagnostic testing full mechanical ins	Cooling performance				
	precion prior to parenase an			Radiator / I	Hoses (visual)
<b>Key</b> S = Scratch	R = Rust C = C	Crack * = Deca	ls W = Significant scuffs	Transmissi	ion
	PT = Paint defect P = P		•	Operation	
			0.77	Noise	
		D	SPT	Clutch	
			SDCW	CV joints	
	Wheel bearings				
S	Brakes				
	Performan	Performance			
	Hand brake				
	Tyres (lowest observed trea				
	JIB OF			Left front	
			(Q)	Right front	
				Left rear	
	W		W	Right rear	
Note: some defec	ts and blemishes may not be	e displayed in the diagra	am	Spare	
	tion Comments	alspia) ca in the diagra		Suspensio	n
				-	n performance
				-	erformance
				Shock abso	
Conditions D	uring Body Inspection		Dry		ioning / Heater
	age and Under Bonnet	Inspection Comm		Operation	ioning/ ricuter
Officer Carrie	ige and officer boffile	. mspection comi	ients —		/ Accessories
				Head lights	
					,
Intorior Com	monts			Tail lights	
Interior Com				Indicators	l sagrania es li este t
Seats:	Good			Dashboard	l warning lights

		Requires	
Frantis	OK	Attention	N/A
Engine Oil level			
Smoke & fumes			
	\( \frac{1}{V} \)		
Engine performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Noise	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Coolant condition	•		
Cooling performance	<b>V</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission		l	<u> </u>
Operation	<b>/</b>		
Noise	<b>/</b>		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes		ı	
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread of	depth of	tyres)	
Left front			5.5 mm
Right front			5.5 mm
Left rear		6	6.0 mm
Right rear		6	6.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	<b>V</b>		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)			~
Number of keys	2		
Central locking	1		
Remote locking	1		
Sat. nav. (basic test only)	1		
Reversing camera	1		
-			

I have read and understood this condition guide:

Marlon Espena

04 Nov 2025

Ajaykumar Muruganandam

Good

Good

Good

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

**Engine Timing Mechanism** 

Dry

Timing Chain

No

Yes

Carpets:

Panels:

Dashboard:

Inspected by:

Published by:

Inspection Date:

**General Comments** 

Kms