


Report ID:	27,158,394	Version:	1
Created:	31 Oct 2025		

Make:	Honda	Model:	Shuttle
Body Style:	Wagon	Year:	2017
Rego No.:	PUN553	Rego Expiry:	18 Sep 2025
WoF Expiry:	01 May 2026	Odometer:	141,734 Kms
Good No.:	27158394	VIN:	7AT08G1XX23200606
Next Service:	no sticker	Service History:	No

diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Dry	<u> </u>
Under Carriage and Under Bonnet Inspection Comments	te

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Flat battery, windscreen cracked, rear view mirror faded, R side windscreen plastic cover missing,

Ī			Dry
			Timing Chain
	Evidence of Can	n Belt Replacement	Yes No Kms
	Inspected by:	Marlon Espena	
	Published by:	Marlon Espena	
	Inspection Date:	31 Oct 2025	

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tince{\tint{\text{\text{\text{\text{\text{\text{\text{\tin}\exitt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}\exitit{\text{\tininte\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinit}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\titt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\tinit}\\ \tittt{\text{\text{\text{\text{\text{\text{\texi}\tittit{\text{\text{\text{\text{\texi}\tittit{\text{\ti}\titt{\text{\text{\text{\text{\texi}\text{\text{\texi}\tinttit{\tert{\texi}\tilittt{\text{\text{\texitile\tii}\tittt{\tiin}\		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		5 mm
Right front			5 mm
Left rear			6 mm
Right rear			6 mm
Spare	N/A		
Suspension			
Suspension performance	V		
Steering performance			
Shock absorbers			
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights	V		
Tail lights	/		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	·		
Window winder FL	·		
Window winder FR	·		
Window winder RL	·		
Window winder RR	·		
Rear view mirrors	·		
Radio (basic test only)	·		
CD (basic test only)	· ·		
Number of keys	1	<u> </u>	Ь
Central locking	V		
Remote locking	· /		
Sat. nav. (basic test only)			
Reversing camera			
		1	

I have read and understood this condition guide: