


Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2019
Rego No.:	MMW607	Rego Expiry:	28 Feb 2026
WoF Expiry:	27 Nov 2026	Odometer:	95,309 Kms
Good No.:	27158421	VIN:	MR0JA3CD000091385
Next Service:	106,000	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
-----------------------------------	-----

Surface rust on front structure

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Samuel Weir		
Published by:	Samuel Weir		
Inspection Date:	12 Nov 2025		

NAME _____

SIGNATURE