

Report ID:	27,158,534	Version:	3
Created:	02 Dec 2025		


Make:	Hyundai	Model:	Elantra
Body Style:	Sedan	Year:	2017
Rego No.:	KZW558	Rego Expiry:	05 Jun 2026
WoF Expiry:	28 Nov 2026	Odometer:	181,825 Kms
Good No.:	27158534	VIN:	KMHD741FMJU561144
Next Service:	191000 kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Interior Comments	
Seats:	Average
Carpets:	Good
Panels:	Average
Dashboard:	Good
General Comments	

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Eleoit Kumar	
Published by:	Shraddha Bhunga	aliya
Inspection Date:	31 Oct 2025	

have read and understood			
his condition guide:	NAME		

	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	/		
Engine performance	/		
Noise	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\ti}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\xi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\ \tittt{\text{\text{\text{\text{\text{\text{\texi}\tint{\text{\text{\text{\texi}\tiliex{\text{\tin}\tiliex{\text{\text{\texi{\text{\text{\texi}\tiliex{\text{\til\til\til\til\til\til\til\titt{\text{\texi{\texi{\texi{\texi{\texi}\tii}\\ \til\tii}\\tii}\\tiint\text{\texi{\texi{\texi{\texi{\texi{\texi{\texi{\texi		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	~		
Noise	/		
Clutch			-
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake			
Tyres (lowest observed tread d	epth of	L tvres)	ļ.
Left front			4.0 mm
Right front			7.0 mm
Left rear			7.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension			
Suspension performance			
Steering performance	~		
Shock absorbers	· /		
Air Conditioning / Heater	•		l
Operation			Π
Electrical / Accessories	•		
Head lights			
Tail lights	~		<u> </u>
Indicators	~		
Dashboard warning lights	✓		
Wipers (front & rear)	·		<u> </u>
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors			<u> </u>
Radio (basic test only)	~		
CD (basic test only)			
Number of keys	1	l	
Central locking	· •		<u> </u>
Remote locking	<u>,</u>		
	•		<u> </u>
			<i>u</i> /
Sat. nav. (basic test only) Reversing camera	V		