

# **Basic Condition Guide**

•	Report ID:	27,158,872	Version:	1
	Created:	04 Nov 2025		


Make:	Holden	Model:	Colorado
Body Style:	Utility	Year:	2019
Rego No.:	MKB332	Rego Expiry:	19 Dec 2025
WoF Expiry:	18 Dec 2025	Odometer:	155,139 Kms
Good No.:	27158872	VIN:	MMU148LK0LH614009
Next Service:	162,000km	Service History:	Yes

### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Kev

Rey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram  $\,$ 

## **Body Inspection Comments**

Right number plate light not working. Radio touch screen doesn't respond in some areas. R bumper step plate gouged.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

# Interior Comments Seats: Good Carpets: Good Panels: Good Dashboard: Good

### **General Comments**

RWD. Windscreen cracked outside cva.

Road Conditions	s During Test Drive	Dry	
Engine Timing N	/lechanism	Timing Chain	
Evidence of Cam	n Belt Replacement	Yes No Kms	
Inspected by:	Sharnae Smith		
Published by:	Sharnae Smith		
Inspection Date:	04 Nov 2025		

	OK	Requires Attention	N/A
Engine			
Oil level	<b>✓</b>		
Smoke & fumes	<b>/</b>		
Engine performance	<b>/</b>		
Noise	✓ ✓		
Coolant condition	<b>V</b>		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission		<u> </u>	
Operation	<b>/</b>		
Noise	/		
Clutch			1
CV joints			1
Wheel bearings	/		
Brakes			
Performance	V		
Hand brake	<b>V</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		•	5 mm
Right front			5 mm
Left rear			4 mm
Right rear			5 mm
Spare	Yes		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	<b>/</b>		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	<b>/</b>		
Tail lights	/		
Indicators	<b>V</b>		
Dashboard warning lights	<b>V</b>		
Wipers (front & rear)	/		
Window winder FL	<b>/</b>		
Window winder FR	/		
Window winder RL	<b>✓</b>		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			1
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)	1		
Reversing camera	1		
<u> </u>			

I have read and understood this condition guide:

NAME SIGNATURE