


Basic Condition Guide

27,160,447 Report ID: Version: 09 Nov 2025 Created:

diagnostic testing ur		oeen driven up to 50km/	Parts have not been dismantled or /h from cold. The Vendor recommends a or an additional charge.	
Note: This report is	not a warranty			
Next Service:	108,351km	Service History:	No	
Good No.:	27160447	VIN:	7AT0DH7DX23104601	
WoF Expiry:	19 Nov 2026	Odometer:	98,349 Kms	
Rego No.:	PZH83	Rego Expiry:	07 Dec 2025	
Body Style:	Wagon	Year:	2012	
Make:	Nissan	Model:	Lafesta	

S = Scratch W = Significant scuffs R = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Dry **Under Carriage and Under Bonnet Inspection Comments**

Interior Comments Seats: Good Good Carpets: Good Panels: Good Dashboard:

General Comments

Stop start light flashing.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes No Kms		
Inspected by:	LukaAjitvan Woerden			
Published by:	Cody O'Neill			
Inspection Date:	01 Nov 2025			

	ОК	Requires Attention	N/A
Engine			
Oil level		•	
Smoke & fumes	>		
Engine performance	/		
Noise	✓		
Coolant condition	\(\times \)		
Cooling performance	/		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	/		
Noise	✓		
Clutch			'
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			7.0 mm
Right front			7.0 mm
Left rear		7	7.0 mm
Right rear		7	7.0 mm
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		_	
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	1		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	✓		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)		1	/
Reversing camera			

I have read and understood this condition guide:

NAME