

Basic Condition Guide

Report ID:	27,161,839	Version:	1
Created:	07 Nov 2025		


KIA	Model:	Sportage
SUV	Year:	2013
GQR368	Rego Expiry:	03 Jul 2026
21 Nov 2026	Odometer:	174,717 Kms
27161839	VIN:	KNAPC811MD7413784
185,000	Service History:	Yes
	SUV GQR368 21 Nov 2026 27161839	SUV Year: GQR368 Rego Expiry: 21 Nov 2026 Odometer: 27161839 VIN:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

itcy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	all seats stained	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive Dry Engine Timing Mechanism Timing Chain Evidence of Cam Belt Replacement Yes No Kms Inspected by: Kyle Kelly Published by: Ryan Stanley

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	/		
Engine performance	✓		
Noise	/		
Coolant condition	\(\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tinx{\text{\text{\text{\text{\text{\text{\text{\tint{\text{\tinit}\\ \text{\texi{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\ti}}\\tittt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\tittitt{\text{\text{\text{\text{\texi}\tittit{\text{\ti}\tittt{\text{\ti}}\tittt{\text{\ti}}\tittt{\text{\ti}\tittt{\tex{\text{\texititt{\texi{\texi{\texi}\tittit{\texi}\tittt{\texi}\tittt{\texititt{\tiint{\tiint{\tiint{\tii}\tittt{\tii}\tittt{\tii}		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	/		
Noise	✓		
Clutch			V
CV joints	✓		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	✓		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		į	5.6 mm
Right front		į	5.7 mm
Left rear		į	5.6 mm
Right rear		(3.1 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	/		<u> </u>
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	✓		
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			V
Reversing camera			/

I have read and understood this condition guide:

03 Nov 2025

Inspection Date:

NAME

SIGNATURE