

•	Report ID:	27,161,860	Version:	2
	Created:	13 Nov 2025		

	ОК	Requires Attention	N/A
Engine	OK	Attention	11/71
Oil level	V		
Smoke & fumes	/		
Engine performance	✓ ✓		
Noise	/		
Coolant condition	·		_
Cooling performance	·		_
Radiator / Hoses (visual)	V		
Transmission			
Operation	/		Π
Noise			
Clutch	V V		
CV joints			\vdash
Wheel bearings	V		\vdash
Brakes			1
Performance	V		
Hand brake		<u> </u>	·
Tyres (lowest observed tread d	epth of	tvres)	
Left front	ори. от		5.0 mm
Right front			5.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance			_
Shock absorbers	· ·		
Air Conditioning / Heater	<u> </u>		
Operation			
Electrical / Accessories		<u> </u>	
Head lights	/		
Tail lights	· /		
Indicators	~		-
Dashboard warning lights	~		_
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR			\vdash
Window winder RL	·		
Window winder RR	<u> </u>		
Rear view mirrors	·		
Radio (basic test only)	· ·		
CD (basic test only) Number of keys	2	<u> </u>	
ivallibel of keys			
Central locking		1	
Central locking	'		
Central locking Remote locking Sat. nav. (basic test only)			


Make:	KIA	Model:	Stinger
Body Style:	Sedan	Year:	2022
Rego No.:	NZG494	Rego Expiry:	09 Jan 2026
WoF Expiry:	18 Dec 2025	Odometer:	108,361 Kms
Good No.:	27161860	VIN:	KNAE551CMN6113688
Next Service:	112,000km	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

1/		_
ĸ	Δ١	₩.

W = Significant scuffs S = ScratchR = RustC = Crack* = DecalsD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Rear bumper moulding refit. RF door seal torn. RR & LR door interior trim torn. F bumper centre moulding missing. LF Tyre minor sidewall cut.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comm	ents	
Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	

RWD. Windscreen crack outside cva.

General Comments

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Sharnae Smith	
Published by:	Henry Manders	
Inspection Date:	04 Nov 2025	

I have read and understood
this condition guide:

NAME			