

Basic Condition Guida

Report ID:	27,161,904	Version:	2
Created:	26 Nov 2025		

	_						
Make:	Isuzu	Model:	D-MAX	-	ОК	Requires Attention	N/A
Body Style:	Utility	Year:	2021	Engine			
Rego No.:	NKF454	Rego Expiry:	30 Nov 2025	Oil level	V		
WoF Expiry:	25 Jun 2026	Odometer:	131,630 Kms	Smoke & fumes	V		
Good No.:	27161904	VIN:	MPATFR40JMT004678	Engine performance	V		
Next Service:	145,267	Service History:	Yes	Noise Noise	/		
lote: This report i	s not a warranty e only. Consideration is ma	do for ago and mileago	Coolant condition	1			
iagnostic testing u	ndertaken. The vehicle has pection prior to purchase a	been driven up to 50km	Cooling performance	/			
			Tot arradutional charge.	Radiator / Hoses (visual)	/		
Key = Scratch F	R = Rust C =	Crack *= Dec	cals W = Significant scuffs	Transmission			
	PT = Paint defect P =		one Chips	Operation	V		
D 00		<u> </u>		Noise	/		
R SC		P	Clutch			1	
				CV joints	/		
	NO VI			Wheel bearings	/		
P 6				Brakes	·		
				Performance	V		
				Hand brake	~		
R SC	18			Tyres (lowest observed tread	depth of	tyres)	
				Left front		3	3.0 mi
			Right front	3.0 mn			
			Left rear	4.0 mm			
S R SC		P W P	Right rear	3.0 mm			
lote: some defect:	s and blemishes may not b	oe displayed in the diag	ıram	Spare	Yes		
Body Inspect	ion Comments			Suspension			
Fresh Cut & Po				Suspension performance	/		
Windscreen st	one chip not in CVA			Steering performance	/		
				Shock absorbers	/		
Conditions Du	ring Body Inspection		Dry	Air Conditioning / Heater			
Under Carria	ge and Under Bonne	et Inspection Com	Operation	/			
				Electrical / Accessories			
				Head lights	/		
				Tail lights	/		
Interior Com	ments		Indicators	/			
Seats:	driver seat worn	& torn	Dashboard warning lights	/			
Carpets:	Good		Wipers (front & rear)	/			
Panels:	Good		Window winder FL	/			
Dashboard:	Good		Window winder FR	/			
General Com	ments		Window winder RL	/			
Partial service			Window winder RR	/			
Equipped with	сапору кеуѕ			Rear view mirrors	/		
				5 11 (1 1 1 1 1 1 1 1		1	1
				Radio (basic test only)	/		

Timing Chain Engine Timing Mechanism Evidence of Cam Belt Replacement Yes No Kms Inspected by: Kilipati Mae Published by: **Bruce Screaton** Inspection Date: 06 Nov 2025

I have read and understood this condition guide:

NAME

SIGNATURE

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

2

1

1