

Basic Condition Guide

| • | Report ID: | 27,161,962 | Version: | 1 |
|---|------------|-------------|----------|---|
| | Created: | 03 Nov 2025 | | |


| Make: | Nissan | Model: | X-Trail |
|---------------|-------------|------------------|-------------------|
| Body Style: | Wagon | Year: | 2014 |
| Rego No.: | PNC554 | Rego Expiry: | 02 Aug 2026 |
| WoF Expiry: | 15 Aug 2026 | Odometer: | 90,188 Kms |
| Good No.: | 27161962 | VIN: | 7AT0DH6LX22001111 |
| Next Service: | can't read | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

| Rey | | | | |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust | C = Crack | * = Decals | W = Significant scuffs |
| D = Dent | PT = Paint defect | P = Pin dent | SC = Stone Chips | |



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Missing tail gate badge,

| Conditions During Body Inspection | Dry |
|---|-------|
| Under Carriage and Under Bonnet Inspection Com | ments |

Engine and trans oil leak,

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Poor | |
| Carpets: | Poor | |
| Panels: | Average | |
| Dashboard: | Average | |

General Comments

Both front seat torn, rear wiper blades not secured, tail gate switch rubber torn, whole body painted blue, faulty locking system, passenger seat adjustment missing, windscreen side plastic cover torn, both front tyre cracked,

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|--------------------|--------------|
| Engine Timing I | Mechanism | Timing Chain |
| Evidence of Can | n Belt Replacement | Yes No Kms |
| Inspected by: | Marlon Espena | |
| Published by: | Marlon Espena | |
| Inspection Date: | 03 Nov 2025 | |

| | ОК | Requires Attention | N/A |
|--------------------------------|----------|-----------------------|----------|
| Engine | J.(| 7.11011 | . 4// 1 |
| Oil level | | V | |
| Smoke & fumes | / | | |
| Engine performance | V | | |
| Noise | / | | |
| Coolant condition | | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | / |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | / | | |
| Hand brake | | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | -,,, | 4 mm |
| Right front | | | 4 mm |
| Left rear | | | 7 mm |
| Right rear | | | 7 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | V | | |
| Steering performance | | | |
| Shock absorbers | | | |
| Air Conditioning / Heater | | | |
| Operation | | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | ✓ | | |
| Indicators | | | |
| Dashboard warning lights | · | | |
| Wipers (front & rear) | | / | |
| Window winder FL | | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | / | | |
| Rear view mirrors | · | | |
| Radio (basic test only) | · | | |
| CD (basic test only) | | | |
| Number of keys | 1 | | |
| Central locking | | V | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | | | |
| Reversing camera | / | | |
| <u> </u> | | | |

I have read and understood this condition guide:

NAME SIGNATURE