

## **Basic Condition Guide**

Report ID:	27,162,427	Version:	4
Created:	15 Dec 2025		

	Nissan	Model:	NV350
Body Style:	Van	Year:	2019
Rego No.:		Rego Expiry:	
WoF Expiry:	10 Dec 2026	Odometer:	126,337 Kms
Good No.:	27162427	VIN:	7AT0DH8RX25112096
Next Service:	136,306 Kms	Service History:	No
iagnostic testing un Ill mechanical inspe (ey = Scratch R :	dertaken. The vehicle has beetion prior to purchase an  = Rust	een driven up to 50km/h d this can be arranged fo track *= Decal	s W = Significant scuff
	(O)=		S SC
s sc		<u> </u>	
M	Mary N		AHY
1		$\parallel \parallel +$	S
	DE II		
$$ $\theta$			
			D SC
	S	P SC D PT SC	S PT SC
ote: some defects	and blemishes may not be	displayed in the diagra	m
Body Inspection	•	. , , , , ,	
Conditions Dur	ing Body Inspection		Dry
	e and Under Bonnet	Inspection Comm	ents
<b>Under Carriag</b>			
Under Carriag			
Under Carriag			
Interior Comm			
Interior Comm	Good		
Interior Comm Seats: Carpets:	Good Average		
Interior Comm Seats: Carpets: Panels:	Good Average Average		
Interior Comm Seats: Carpets: Panels: Dashboard:	Good Average Average Good		
Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	Good Average Average Good	rt the iccuo will be	fived in the new year
Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	Good Average Average Good	rt, the issue will be	fixed in the new year.
Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	Good Average Average Good	rt, the issue will be	fixed in the new year.
Interior Comm Seats: Carpets: Panels: Dashboard: General Comn Loud whine in d	Good Average Average Good nents riveline - awaiting pa		fixed in the new year.
Interior Comm Seats: Carpets: Panels: Dashboard: General Comn	Good Average Average Good nents riveline - awaiting pa	rt, the issue will be  Dry  Timing Chain	fixed in the new year.

	OK	Requires Attention	
Engine	<u> </u>	Accention	14/74
Oil level	V		
Smoke & fumes	<b>V</b>		
Engine performance			
Noise	\( \tau \)		
Coolant condition	<i>-</i>		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	<b>V</b>		<u> </u>
Noise	<i>y</i>		
Clutch			
CV joints	<b>4</b>		_
Wheel bearings	1		
Brakes			
Performance	./		
Hand brake			
		1	
Tyres (lowest observed tread d	eptn of		7.5
Left front			7.5 mm
Right front			7.5 mm
Left rear			7.0 mm
Right rear			6.5 mm
Spare	Yes		
Suspension		T	
Suspension performance			
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		T	
Operation	/		
Electrical / Accessories		,	
Head lights	<b>/</b>		
Tail lights	<b>/</b>		
Indicators	<b>V</b>		
Dashboard warning lights			
Wipers (front & rear)	/		
Window winder FL	•		
Window winder FR	/		
Window winder RL			V
Window winder RR			V
Rear view mirrors	<b>/</b>		
Radio (basic test only)	/		
CD (basic test only)	<b>V</b>		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	1		
-			

I have read and understood this condition guide:

Inspection Date: 14 Dec 2025

Inspected by:

Published by:

NAME

Troy Smith

Andrey Dyblenko

SIGNATURE