

Basic Condition Guide

•	Report ID:	27,162,616	Version:	3
	Created:	21 Nov 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	V		
Engine performance	/		
Noise	/		
Coolant condition	V		
Cooling performance	V		
Radiator / Hoses (visual)	V		
Transmission			
Operation	V		
Noise	/		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	V		
Hand brake	V		
Tyres (lowest observed tread	depth of	tyres)	
Left front	1		4 mn
Right front			4 mn
Left rear			4 mn
Right rear			4 mn
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	V		1
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	1	 	
Number of keys	1	<u> </u>	L
Central locking	1	1	1
Remote locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Sat. nav. (basic test only) Reversing camera			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
neversing carriera			

Make:	BMW	Model:	1161
Body Style:	Hatchback	Year:	2012
Rego No.:	REN171	Rego Expiry:	01 Feb 2026
WoF Expiry:	01 Dec 2026	Odometer:	32,062 Kms
Good No.:	27162616	VIN:	WBA1A12030E949921
Next Service:	42062kms	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

\mathbf{v}	~~.
n	eν

rcy				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chips in windscreen.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

All good

Interior Comments	
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Vehicle drove well.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jayden Roxburgh	
Published by:	Jayden Roxburgh	
Inspection Date:	21 Nov 2025	

have read and understood
this condition quide

NAME			