

Report ID:	27,163,449	Version:	4
Created:	15 Nov 2025		

Make:	Hyundai	Model:	Getz	
Body Style:	Hatchback	Year:	2009	
Rego No.:	NNS129	Rego Expiry:	10 Sep 2026	
WoF Expiry:	17 Jun 2026	Odometer:	138,146 Kms	
Good No.:	27163449	VIN:	KMHBT51DMAU946372	
Next Service	148,147kms	Service History:	No	
agnostic testing	undertaken. The vehicle has b spection prior to purchase an	een driven up to 50km/l d this can be arranged f -		
= Scratcn = Dent	R = Rust $C = CPT = Paint defect$ $P = P$			
_ Dent	TI – I allit delect P = P		пс спрз	
	S	P		
	$(0)_{\mathbb{F}}$		(O)	
SC				
	110			
	$\{\parallel \parallel $			
sc	ALC ME			
	JIB OF			
			(Q)	
	S	PP	SD	
	ts and blemishes may not be tion Comments	e displayed in the diagra	ım 	
Dody IIIspec	don comments			
C 1::: C			D	
	uring Body Inspection		Dry	
Under Carri	age and Under Bonnet	Inspection Comm	ents	
Interior Con	ments			
Seats:	Average			
Carpets:	Average			
	Average			
Panels:				

	01/	Requires	
Engine	OK	Attention	N/A
Oil level	V		<u> </u>
Smoke & fumes	-		
	1		
Engine performance	V		
Noise	1		
Coolant condition	-		
Cooling performance	-		
Radiator / Hoses (visual)			
Transmission		Γ	
Operation	•		
Noise	-		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread	depth of	tyres)	
Left front			1.0 mm
Right front		3	3.0 mm
Left rear		6	6.0 mm
Right rear		2	1.0 mm
Spare	Yes		
Suspension			
Suspension performance	'		
Steering performance	'		
Shock absorbers	1		
Air Conditioning / Heater			
Operation		V	
Electrical / Accessories			
Head lights	V		
Tail lights	1		
Indicators	1		
Dashboard warning lights	V		
Wipers (front & rear)	1		
Window winder FL			
Window winder FR	V		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	1		
CD (basic test only)	+ -		-
Number of keys	2	l	
Central locking	1	1	1
Remote locking	· ·		
			J
Sat. nav. (basic test only)			
Reversing camera		<u> </u>	

*** THIS HYUNDAI GETZ HAS BEEN RE-REGISTERED DUE TO ACCIDENT DAMAGE, THERE IS A FLAG REGISTERED WITH NZTA TO SAY THIS ***			
Road Condition	s During Test Drive	Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No	Kms
Inspected by:	LukaAjitvan Woer	erden	
Published by:	Jade Ackroyd		
Inspection Date:	05 Nov 2025		
		'	

I have read and understood
this condition guide:

Dashboard:

General Comments

Average

Subwoofer wiring. A/C fail and heater control hard to turn.

NAME			