

Report ID: 27,163,648		Version:	1
Created:	05 Nov 2025		

	1000	Raci	c Condition Guide	Report ID: 27, 163,62
	nuel	<u>Dasi</u>		Created: 05 Nov 2
Make:	Suzuki	Model:	Swift	
Body Style: Hatchback		Year:	2019	Engine
Rego No.: MFY36		Rego Expiry:	15 Nov 2025	Oil level
WoF Expiry:	19 Nov 2026	Odometer:	49,114 Kms	Smoke & fumes
Good No.:	27163648	VIN:	JSAAZC33S00114116	
Next Service:	58,400 Kms	Service History:	Yes	Engine performance
Note: This report is	not a warranty			Noise
This report is a guide diagnostic testing ur	Coolant condition			
	ection prior to purchase and			Cooling performance
Key				Radiator / Hoses (visua
$S = Scratch \qquad R = Rust \qquad \qquad C = Crack \qquad * = Decals \qquad \qquad W = Significant scuffs$				Transmission
D = Dent P1	Operation			
S	Noise			
				Clutch
	CV joints			
	SP			
M				Brakes
\mathcal{H}				Performance
				Hand brake
Solo				Tyres (lowest observed
				Left front
			S	Right front
	\angle			Left rear
	Right rear			
Note: some defects	Spare			
Body Inspection	Suspension			
				Suspension performan
				Steering performance
				Shock absorbers
Conditions Dur	ing Body Inspection		Dry	Air Conditioning / He
Under Carriag	e and Under Bonnet	Inspection Comm	ents	Operation

Interior Comments	
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes No Kms		
Inspected by:	Kyle Kelly			
Published by: Jayson Rodriguez		Z		
Inspection Date:	04 Nov 2025			

		Requires	
	OK	Attention	N/A
Engine			1
Oil level	~		
Smoke & fumes	\(\tau \)		<u> </u>
Engine performance	/		
Noise	~		
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	/		
Transmission			
Operation	~		
Noise	~		
Clutch	/		
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	1		
Hand brake	~		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		Ę	5.2 mm
Right front		ţ	5.6 mm
Left rear			4.3 mm
Right rear			2.9 mm
Spare	N/A		
Suspension			
Suspension performance	~		
Steering performance	1		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	/		
Tail lights	1		
Indicators	1		
Dashboard warning lights	~		_
Wipers (front & rear)	1		
Window winder FL	1		<u> </u>
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1		
Radio (basic test only)	~		-
			<u></u>
CD (basic test only)	1		
Number of keys	· ·		
Central locking	1		
Remote locking	~		<u> </u>
Sat. nav. (basic test only)	.,		
Reversing camera	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		

I have read and understood this condition guide:

NAME SIGNATURE