

Basic Condition Guide

Report ID:	27,165,252	Version:	1
Created:	03 Nov 2025		

U	ntue	S Basi	c Condition Guide	Created: 03 Nov 2025				
Make:	Subaru	Model:	Impreza			Requires		
Body Style:	Wagon	Year:	2008	Facina	OK	Attention	N/A	
Rego No.:	MJJ496	Rego Expiry:	12 Sep 2026	Engine				
WoF Expiry:	25 Mar 2026	Odometer:	715,805 Kms	Oil level	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Good No.:	27165252	VIN:	7AT0GF09X19006722	Smoke & fumes	1			
Next Service:		Service History:	No	Engine performance	1			
Note: This report i	s not a warranty		Noise Coolant condition	1				
his report is a guic liagnostic testing u	de only. Consideration is madundertaken. The vehicle hat	de for age and mileage. Seen driven up to 50km	Parts have not been dismantled or /h from cold. The Vendor recommends a		V			
ull mechanical insp	pection prior to purchase an	nd this can be arranged f	or an additional charge.	Cooling performance Radiator / Hoses (visual)	V			
Кеу				Transmission				
	R = Rust C = C PT = Paint defect P = P			Operation 🗸				
) = Delit F				Noise	1			
S P SC W	S	scw scw	W	Clutch	_		-	
				CV joints	V			
	$\mathcal{O}_{\mathcal{F}}$		(\bigcirc)	Wheel bearings	1			
SC W		<u> </u>		Brakes				
			THE REPORT OF THE PERSON OF TH	Performance	V			
			SC	Hand brake	V			
sc w	HOS II			Tyres (lowest observed tread depth of tyres)				
SC W				Left front	черитог	tyres)	5 mm	
		+		Right front		-	7 mm	
				Left rear			5 mm	
SC	W	SC W P SC W	Right rear			5 mm		
ulatar sama dafast	s and blomishes may not be	displayed in the diagram		Spare	Yes			
	s and blemishes may not be tion Comments	e dispiayed in the diagra	MIII 	Suspension				
body mspece				Suspension performance	V			
				Steering performance	1			
				Shock absorbers	1			
Conditions Du	uring Body Inspection		Air Conditioning / Heater					
	ge and Under Bonnet	t Inspection Comm	Operation	V				
	3			Electrical / Accessories				
				Head lights	V			
				Tail lights	1			
Interior Com	ments			Indicators	1			
Seats:	Average			Dashboard warning lights	1			
Carpets:	Average			Wipers (front & rear)	1			
Panels:	Average			Window winder FL	1			
Dashboard:	Average			Window winder FR	1			
General Com			Window winder RL	1				
				Window winder RR	/			
				Rear view mirrors	1			
				Radio (basic test only)	1			
Road Condition	ons During Test Drive	Dry		CD (basic test only)			1	
		Unknown		Number of keys	1			
Englie Tilling Mechanism								

I have read and understood this condition guide:

Tyler Le Bherz

Tyler Le Bherz

03 Nov 2025

Evidence of Cam Belt Replacement

Inspected by:

Published by:

Inspection Date:

Yes

No

NAME SIGNATURE

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1