

Basic Condition Guide

Report ID:	27,166,298	Version:	2
Created:	24 Nov 2025		

Engine

OK

Requires

Attention


N/A

Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2018
Rego No.:	LDE634	Rego Expiry:	22 May 2026
WoF Expiry:	03 Dec 2026	Odometer:	297,850 Kms
Good No.:	27166298	VIN:	MR0JA3DD000343053
Next Service:	307000 kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Kev

,				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chins	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Rear impact damage. Headliner stains. Tailgate support strap loose RHS. Rear canopy window locks not working, latches installed. Right taillight hazy. High stop light cracked.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Engine undertrays rust. Trailer connector loose.

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Poor	
Dashboard:	Average	

General Comments

ODO: 297786 kms. Partial service history. E-Road installed. Steering controls faded. Aftermarket canopy light. Front bumper lower grille refit. Right headlight bulb cover missing.

Road Conditions During Test Drive		s During Test Drive	Dry	
Engine Timing Mechanism		Леchanism	Timing Chain	
Evidence of Cam Belt Replacement		n Belt Replacement	Yes No Kms	
Inspected by: Eleoit Kumar		Eleoit Kumar		
	Published by:	Phoenix Sheffield		
	Inspection Date:	17 Nov 2025		

have read and understood		
his condition guide:	NAME	

Oil level	/		
Smoke & fumes	V		
Engine performance	/		
Noise	V V		
Coolant condition	/		
Cooling performance	1		
Radiator / Hoses (visual)	'		
Transmission			
Operation	/		
Noise	/		
Clutch			/
CV joints			V
Wheel bearings	/		
Brakes			
Performance	1		
Hand brake	~		
Tyres (lowest observed tread o	lepth of	tyres)	•
Left front			6.0 mm
Right front			6.0 mm
Left rear			6.0 mm
Right rear			6.0 mm
Spare	Yes		
Suspension	'		
Suspension performance	1		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	1		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	V V V V V		
Window winder FL	/		
Window winder FR	/		
Window winder RL			
Window winder RR	'		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	~		
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			V
Reversing camera	/		

SIGNATURE		