

-	Report ID:	27,166,845	Version:	1	
	Created:	13 Nov 2025			

Requires Attention

1

N/A

5 mm

	Basic Condition Guide		Report ID:	27,166,845	Ve	rsion:	
	omer	S Das	Condition Guide	Created:	13 Nov 2025		
Make:	Toyota	Model:	Hilux			ОК	Rec
Body Style:	Utility	Year:	2017	Engine		OK	Atte
Rego No.:	KSM877	Rego Expiry:	01 Aug 2026	Oil level			
WoF Expiry:	05 Mar 2026	Odometer:	164,159 Kms	Smoke & fu	ımor	1	-
Good No.:	27166845	VIN:	MR0JA3CD200090738			1	-
Next Service:	163056 kms	Service History:	Yes	Engine per	Torriance	1	\vdash
Note: This report i	s not a warranty	'		Coolant co	ndition	V	-
diagnostic testing u	ındertaken. The vehicle has b	een driven up to 50km/	arts have not been dismantled or h from cold. The Vendor recommends a		rformance	1	┢
full mechanical inspection prior to purchase and this can be arranged for an additional charge.				Hoses (visual)	V		
Key				Transmiss			
	R = Rust C = C PT = Paint defect P = P		als W = Significant scuffs one Chips	Operation	1011	V	Γ
— Delit F				Noise		1	-
D		SD* SD*	SD	Clutch			-
				CV joints		1	\vdash
	(O)_		S D	Wheel bea	win a.c	<i>'</i>	\vdash
S				Brakes	rings		
			HIV				Т
			S	Performan		/	├
				Hand brak		V	<u> </u>
SOO				Tyres (lowest observed tread depth of tyres)			tyres)
`	The contract of the contract o		SD*	Left front			
				Right front			
				Left rear			
		SD* SD*	SD	Right rear			
Note: some defect:	s and blemishes may not be	e displayed in the diagr	am	Spare		Yes	

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments		
Seats:	Poor	
Carpets:	Poor	
Panels:	Poor	
Dashboard:	Average	

General Comments

Wing my switch broken and interior door panel missing,rattling sound engine bay,R tail light cracked, L rear interior door panel torn, driver carpet torn, underbody rust, trans axle seal leak (drive shaft), both wing mirror cover not secured.

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Marlon Espena			
Published by:	Marlon Espena			
Inspection Date:	13 Nov 2025			

have read and understood		
this condition guide:	NAME	

Right front			5	mm
Left rear			7	mm
Right rear			7	mm
Spare	Yes			
Suspension				
Suspension performance	'			
Steering performance	/			
Shock absorbers	/			
Air Conditioning / Heater				
Operation	/			
Electrical / Accessories				
Head lights	/			
Tail lights		~		
Indicators	1			
Dashboard warning lights	1			
Wipers (front & rear)	/			
Window winder FL	/			
Window winder FR	/			
Window winder RL	/			
Window winder RR	/			
Rear view mirrors	/			
Radio (basic test only)	/			
CD (basic test only)	/			
Number of keys	1			
Central locking	/			
Remote locking	/			
Sat. nav. (basic test only)				✓
Reversing camera	'			