

Report ID:	27,167,048	Version:	1	
Created:	04 Nov 2025			

		Pasi	a Canditian Cuida	Report ID:	27,167,048	Ve	rsion: 1	
	urner	S Basi	c Condition Guide	Created:	04 Nov 2025			
			D. 50				Requires	
Make:	Mazda	Model:	Bt-50			OK	Attention	N/A
Body Style:	Utility	Year:	2018	Engine				
Rego No.:	LDC600	Rego Expiry:	07 Jan 2026	Oil level		'		
WoF Expiry:	13 Dec 2025	Odometer:	167,912 Kms	Smoke & fumes		/		
Good No.:	27167048	VIN:	MM0UR0YG100772894	Engine performance		/		
Next Service: 167,000 Service History: No			Noise		/			
lote: This report is not a warranty his report is a quide only. Consideration is made for age and mileage. Parts have not been dismantled or					Coolant condition			
liagnostic testing undertaken. The vehicle ha been driven up to 50km/h from cold. The Vendor recommends a ull mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling pe	erformance	'		
				Radiator / H	Hoses (visual)	/		
	R = Rust $C = C$: Crack *= Deca	ls W = Significant scuffs	Transmiss	ion			
D = Dent I	PT = Paint defect P = P	in dent SC = Sto	ne Chips	Operation		/		
		PP	P	Noise		/		
-				Clutch				/
				CV joints		/		
	MA UT			Wheel bea	rings	/		
—— <i>f</i>				Brakes				
				Performan	ce	1		
				Hand brake	e	1		
	18			Tyres (lowest observed tread depth of tyres)				
				Left front				8 mm
				Right front				8 mm
				Left rear				8 mm
P D				Right rear				8 mm
Note: some defect	ote: some defects and blemishes may not be displayed in the diagram				Spare Yes			
Body Inspect	tion Comments			Suspensio	on			
Canopy door h				Suspension	n performance	1		
Both rear stop	0			Steering pe	erformance	~		
Left taillight cracked Both sills pin-dent				Shock abso	orbers	~		
Conditions During Body Inspection Dry			Air Condit	ioning / Heater	_	,		
Under Carriage and Under Bonnet Inspection Comments						V		
Underbody oxidation				Electrical / Accessories				
				Head lights	S		V	
				Tail lights		~		
Interior Comments			Indicators		1			
Seats:	eats: driver seat worn & torn		Dashboard	l warning lights	~			
Carpets:	ets: Good		Wipers (fro	nt & rear)	/			
Panels:	Panels: Average		Window w	inder FL	~			
Dashboard:	Dashboard: Average			Window w	inder FR	1		
General Comments			Window w	inder RL	1			
							-	

Dustriboura:	/ trolugo					
General Comments						
Left headlight not working						
Reverse camera	Reverse camera faulty					
Squeaking noise from front suspension						
Road Condition	Road Conditions During Test Drive			_		
Engine Timing I	Engine Timing Mechanism					
Evidence of Can	Evidence of Cam Belt Replacement		No Kn	าร		
Inspected by:	Kilipati Mae					
Published by:	Kilipati Mae					
Inspection Date:	04 Nov 2025					

		,		
Engine Timing N	Mechanism	Timing Chain	1	
Evidence of Can	n Belt Replacement	Yes	No	Kms
Inspected by:	Kilipati Mae			
Published by:	Kilipati Mae			
Inspection Date:	04 Nov 2025			
		_		

I have read and understood this condition guide:

Window winder RR Rear view mirrors

Radio (basic test only) CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1

1 3

1

1