

Basic Condition Guide


•	Report ID:	27,167,575	Version:	2
	Created:	21 Nov 2025		

	ОК	Requires Attention	
Engine			_
Oil level	/		
Smoke & fumes	1		
Engine performance	1		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	1		
Noise	1		
Clutch	<i>'</i>		
CV joints			
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	1		
Tyres (lowest observed tread d	enth of	tvres)	
Left front	Cpuror		3.0 mm
Right front			3.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension	103		
Suspension performance	1	I	
Steering performance	•		
Shock absorbers	•		
Air Conditioning / Heater			
		·	
Operation Electrical / Accessories			
		l	
Head lights	<i>'</i>		
Tail lights Indicators			
	V		
Dashboard warning lights	\(\)		
Windowwindor Fl	<i>'</i>		
Window winder FL	.,	-	
Window winder FR	-		
Window winder RL			
Window winder RR	_	-	
Rear view mirrors	/		
Radio (basic test only)		"	
CD (basic test only)	4		<u> </u>
Number of keys	1	1	
Central locking	/		<u> </u>
Remote locking			
Sat. nav. (basic test only)			
Reversing camera			

Make:	Nissan	Model:	Caravan
Body Style:	Van	Year:	2013
Rego No.:	LGU901	Rego Expiry:	25 Sep 2026
WoF Expiry:	01 Dec 2026	Odometer:	226,490 Kms
Good No.:	27167575	VIN:	7AT0DH06X17011056
Next Service:	236,000	Service History:	Yes
lote: This report is	not a warranty		

full mechanical inspection prior to purchase and this can be arranged for an additional charge.

itey				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Paint work poor and coming off in areas.

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments Seats: Average Average Carpets: Panels: Average Dashboard: holes previous equipment **General Comments**

Air conditioning nw, heating ok. Radio power cuts out intermittently

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Gary Adams	
Published by:	Saxon Ewen	
Inspection Date:	10 Nov 2025	

I have	read	and	understood
thic co	nditi	on a	uido

NAME			

SI	GN	JA.	ΓU	RF