

Basic Condition Guide

•	Report ID: 27,168,209		Version:	3
	Created:	17 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Engine performance	\(\times \)		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	1		
Noise	1		
Clutch			
CV joints	_		
Wheel bearings	~		
Brakes		1	
Performance	/		
Hand brake	1	 	
Tyres (lowest observed tread d	enth of	tvres)	
Left front	Cptiroi		3.0 mm
Right front			3.0 mm
Left rear			2.0 mm
Right rear			3.0 mm
Spare	Yes		
Suspension	103		
Suspension performance	1		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation Operation	1	<u> </u>	
Electrical / Accessories			
	/		
Head lights Tail lights	~		
Tail lights Indicators	1		
Dashboard warning lights			
	/		
Window windor Fl	<i>'</i>	-	
Window winder FL Window winder FR	<i>'</i>	-	
		-	
Window winder RL Window winder RR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	-	
	.,	-	
Rear view mirrors	V	-	
Radio (basic test only)	7	-	
CD (basic test only)	1	<u> </u>	L
Number of keys		1	
Central locking	<i>'</i>	-	
Remote locking			
	I		
Sat. nav. (basic test only) Reversing camera			

Make:	Toyoto	Model:	Corolla
Make:	Toyota	Model:	Corolla
Body Style:	Sedan	Year:	2014
Rego No.:	HGK509	Rego Expiry:	04 Dec 2025
WoF Expiry:	20 Nov 2026	Odometer:	125,596 Kms
Good No.:	27168209	VIN:	MR053REH205250788
Next Service:	135,594 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key * = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Interior Comments Seats: Average Average Carpets: Panels: Average Dashboard: Steering wheel worn.

General Comments

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Daryll Timms		
Published by:	Leon Sun		
Inspection Date:	04 Nov 2025		

I have	read	and	understood
thic co	nditi	on a	uido

NAME			